



0000106185

ORIGINAL

P.O. Box 38
15996 Ironwood Drive,
Dolan Springs, AZ 86441
928-767-3713 Fax: 928-767-3053
Tiptonwater@Frontiernet.net

December 14th, 2009

Compliance Department
Arizona Corporation Commission
1200 West Washington St.
Phoenix, AZ 85007

RE: ADEQ Compliance Status Report
W-02105A-07-0510 Decision 70837

Here is the ADEQ compliance report due for the month of November. We had our inspection from ADEQ on December 8th. We passed with flying colors and will be providing you with this report as soon as we receive it. We also expect that ADEQ will update our official compliance status shortly as well. We are now up-to-date with all of the monitoring and reporting requirements since we have completed and submitted all of our required quarterly water tests and have filed Mt. Tipton Water Company's 2007 Consumer Confidence Report.

The new ADEQ inspector for our area, Craig Beeson, seemed very impressed with all that had been accomplished. We request to be informed by staff whether we will need to continue filing this report in the future.

Any additional information you need, please contact me anytime, 928-715-6422.

Thank you very much,

L. Tim Clark
Field Manager
Mt. Tipton Water Company

Arizona Corporation Commission
DOCKETED


DEC 16 2009

DOCKETED BY

AZ CORP COMMISSION
DOCKET CONTROL

2009 DEC 16 A 9:33

RECEIVED



P.O. Box 38
15996 Ironwood Drive,
Dolan Springs, AZ 86441
928-767-3713 Fax: 928-767-3053
Tiptonwater@Frontiernet.net

**Arizona Department of Environmental Quality Compliance Report
(W-02105A-07-0510 Decision 70837)**

Mt. Tipton Water Company has been working on the following compliance items for the ADEQ:

The MPA test completed previously for the #8 Horizontal well #55-601848 passed and indicated that it was not contaminated by surface water. Now, we will be able to proceed with taking the steps towards bringing this water source into the system as finances allow.

The above applies to Item #9 under "Major Deficiencies," in reference to ADEQ Inspection Report ID # 123663, hereafter referred to as ADEQ Report.

The Iron well #2 has been cleaned and had a new pump installed and now has American-made black Iron pipe in the well and the well head. Removing galvanized pipe from the system is an ongoing project. It would not be practical or cost-effective to take every well out of operation in order to change out the pipe. Since we are in the process of redoing most of our wells with ARRA stimulus funding, we are replacing the pipe as we proceed.

The above applies to Item #3 under "Major Deficiencies," in reference to ADEQ Report.

We have replaced 37 older meters during November. This should decrease water loss as old meters often do not accurately record customer water usage.

The above applies to Item #9 under "Minor Deficiencies," in reference to ADEQ Report.

The access ladders were removed from Kevin's tanks.

The above applies to Item #5 under "Minor Deficiencies," in reference to ADEQ Report.

A backflow and an air gap were installed on the standpipe.

The above applies to Item #18 under "Major Deficiencies," in reference to ADEQ Report.

All of the exposed PVC in the system has been wrapped to protect it from UV exposure.

The above applies to Item #2 under "Inspection Recommendations," in reference to ADEQ Report.