



0000107296

ORIGINAL

P.O. Box 38
15996 Ironwood Drive,
Dolan Springs, AZ 86441
928-767-3713 Fax: 928-767-3053
Tiptonwater@Frontiernet.net

February 11th, 2010

Compliance Department
Arizona Corporation Commission
1200 West Washington St.
Phoenix, AZ 85007

RE: ADEQ Compliance Status Report
W-02105A-07-0510 Decision 70837

Here is the ADEQ compliance report due for the month of January. Some small and ongoing issues were addressed last month. We are currently in compliance with ADEQ. Attached to the report is the appropriate page from the inspection report to reference what has been completed.

Any additional information you need, please contact me anytime, 928-715-6422.

Thank you very much,

L. Tim Clark
Field Manager
Mt. Tipton Water Company

Arizona Corporation Commission
DOCKETED

FEB 16 2010

DOCKETED BY *MM*

AZ CORP COMMISSION
DOCKET CONTROL

2010 FEB 16 A 10:45

RECEIVED

ADEQ Compliance Report
Mt. Tipton Water Company

Mt. Tipton has been working on the following items for ADEQ:

In reference to ADEQ Inspection Report ID # 151526, hereafter referred to as ADEQ Report, Site #6, Well 6, ADWR # 55-601846, Item # 2.

The electrical control panels were locked with the switches in the off position to secure them against tampering.

Item # 3. A pipe cap was installed on the intake line to secure it and seal it from atmospheric contamination.

In reference to ADEQ Report, Site #2, Well #2, ADWR # 55-508835, Item #1. This well has been rehabbed and will be online as soon as the disinfection process is completed.

As far as general water loss issues, we are taking actions to address this on an ongoing basis. We have identified and repaired three leaks in the system recently. The first leak was on Edgemont St. between Pierce Ferry Rd. and 8th St. Another was on Laurel Dr. between 15th St. and 16th St. The last was at a meter box on Pierce Ferry Rd. north of Bullhead St. Additionally, 9 main line valves have been located and exercised. Also, 6 meters were installed, as old meters that do not function properly are a contributing factor in water loss.

Site #2, Well #2, ADWR# 55-508835

- 1) **This well is presently under rehabilitation and is off-line.**

LDS Site #3, Well# 3, ADWR # 55-520733

- 1) **No recommendations**

Chambers Site #5, Well# 5, ADWR 55-510178

- 1) **There is now a water meter in place.**
- 2) **The galvanized pipe on the pressure tank is to be removed and replaced in the near future. The gauge reading was 75psi.**
- 3) **Locks are on the electrical control panels.**

Site #6, Well #6, ADWR # 55-601846

- 1) **This well has collapsed and is off-line.**
- 2) **Please lock the electrical control panels with the switches in the "off" to secure the panels against tampering.**
- 3) **Please attach a pipe cap on the intake line up stream from the valve to water system to secure the line. Presently the line is open to the atmosphere and contamination.**

Site #7, Well # 7, ADWR 55-601847

- 1) **Please install a fence around the well site to secure it.**

Site # 8, Well # 8, ADWR 55-601848 (This was Well #9B)

- 1) **Please install a fence around the well site in order to secure it.**
- 2) **The sampling tap is properly filed.**