

ORIGINAL

Stephen A Cockrum
5328 Corral Drive
Hereford, Az 85615



0000090825


47

Arizona Corporation Commission
DOCKETED

November 24, 2008

NOV 23 2008

Docket Control
Arizona Corporation Commission
1200 West Washington Street



Phoenix, AZ 85007 W-20454A-06-0248, W-20453A-06-0251, W-20454A-06-0251, W-01646A-06-0251, W-01868A-06-0251,
W-02235A-06-0251, W-02316A-06-0251, W-02230A-06-0251, W-01629A-06-0251, W-02240A-06-0251

RE: Intervenor Response to the letter dated November 20, 2008 by Mr. Greg Sorensen, Director of Operations, Western Division, Algonquin Water Services L.L.C. addressing Compliance with Decision No. 68826, Docket Nos. W-20453A-06-0247 et al, the Proposed Modification to the Capital Improvements per Exhibit "B", Northern Sunrise Water Company-Coronado Estates and Sierra Sunset Systems.

Mr. Sorensen states in the above referenced letter that "many improvements have been made, much data has been collected, and economic conditions have changed which has led to the change in modifications proposed in Exhibit B". He further references the physical interconnection between the two systems, the fact that all services have been replaced and meters installed in the Sierra systems, and the installation of well meters at both wells. I will presume that these actions constitute what is described as "many improvements". He does not, however, explain specifically what economic conditions have changed and how those changes have specifically affected the change to the Capital Improvement schedule for Exhibit B.

It is not clearly stated in either Mr. Sorensen's letter or the report prepared by Westland Resources, Inc. and attached to the Sorensen letter as Exhibit 1 that the information presented reflects in any way the impact of the CC&N extension request presently before the Commission in the current matter. If the extension request is granted by the Commission, the near term impact of that decision should be a part of the engineering report.

Mr. Sorensen also attached a "Water Use Data Sheet" for the combined (interconnected) companies of Coronado Estates and Sierra Sunset for the period beginning November 2007 and terminating in October 2008. For the period described, Northern Sunrise Water Company reports Gallons Sold (Thousands) of 15,622, Gallons Pumped (Thousands) of 18,486; a difference of 2,864,000 Gallons. This difference represents a shortage of 15.5%, a figure that is beyond a number that would otherwise be viewed as "reasonable". There may exist very legitimate reasons for this otherwise excessive variance, but I would ask that those reasons be made a part of the record.

Respectfully Submitted,

Stephen A Cockrum

DOCKET CONTROL
AZ CORP COMMISSION

NOV 25 4 59 PM 2008

RECEIVED