

ORIGINAL

NEW APPLICATION



0000166961

Forest
Highlands



RECEIVED

2015 NOV 18 P 2:00

AZ CORP COMMISSION
DOCKET CONTROL

W-02493A-15-0392

From: Forest Highlands Water Company
2425 William Palmer
Flagstaff, Arizona 86005


November 16, 2015

To: Docket Control
Arizona Corporation Commission
1200 West Washington Street
Phoenix, Arizona 85007

Arizona Corporation Commission

DOCKETED

NOV 18 2015



Attached is an application by the Forest Highlands Water Company for approval of a (new) Cross-Connection Tariff. The purpose of this tariff is to protect the Forest Highlands Water Company water from the possibility of contamination caused by the backflow of contaminants that may be present in the customer's premises.

The Forest Highlands Water Company did receive a CROSS-CONNECTION OR BACKFLOW TARIFF that was originally effective on October 26, 2004. However, it was recommended that we file new forms so that our tariff would reflect the latest rules.

Thank you for your attention in this matter.

Sincerely,

Bill Strauss
Director of Public Works
Forest Highlands Golf Club
Direst - (928) 525-5264
bstrauss@fhgc.com

Forest Highlands Utilities 2425 William Palmer Flagstaff, Arizona 86005
Office (928) 525-5244 Fax (928) 525-5254

CROSS-CONNECTION OR BACKFLOW TARIFF

PURPOSE:

The purpose of this tariff is to protect Forest Highlands
Water Company ("Company") water from the possibility of
contamination caused by the backflow of contaminants that may be present on the
customer's premises by requiring the installation and periodic testing of backflow-
prevention assemblies pursuant to the provisions of the Arizona Administrative Code
("A.A.C.") R14-2-405.B.6 and A.A.C. R18-4-215.

REQUIREMENTS:

In compliance with the Rules of the Arizona Corporation Commission
("Commission") and the Arizona Department of Environmental Quality ("ADEQ"),
specifically A.A.C. R14-2-405.B.6 and A.A.C. R18-4-215 relating to backflow
prevention:

1. The Company may require a customer to pay for and to have installed a
backflow-prevention assembly if A.A.C. R18-4-215.B or C applies.
2. A backflow-prevention assembly required to be installed by the customer
under Paragraph 1 of this tariff shall comply with the requirements set forth in
A.A.C. R18-4-215.D and E.
3. Subject to the provisions of A.A.C. R14-2-407 and 410, and in accordance
with Paragraphs 1 and 7 of this tariff, the Company may terminate service or
may deny service to a customer who fails to install a backflow-prevention
assembly as required by this tariff
4. The Company shall give any existing customer who is required to install a
backflow-prevention assembly written notice of said requirement. If A.A.C.
R14-2-410.B.1.a. is **not** applicable, the customer shall be given thirty (30)
days from the time such written notice is received in which to comply with
this notice. If the customer can show good cause as to why he cannot install
the backflow-prevention assembly within thirty (30) days, the Company or
Commission Staff may suspend this requirement for a reasonable period of
time.

****FOR OFFICIAL USE ONLY****

Effective Date: _____

Company Name: Forest Highlands Water Company Page 2 of 2

5. Testing shall be in conformance with the requirements of A.A.C. R18-4-215.F. The Company may require the customer to pay to have the backflow-prevention assembly tested as long as the Company does not require an unreasonable number of tests.
6. The customer shall provide the Company with records of installation and testing. For each backflow-prevention assembly, these records shall include:
 - a. assembly identification number and description;
 - b. location
 - c. date(s) of test(s);
 - d. description of repairs and recommendations for repairs made by tester; and
 - e. the tester's name and certificate number.
7. In the event the backflow-prevention assembly does not function properly or fails any test, and an obvious hazard as contemplated under A.A.C. R14-2-410.B.1.a. exists, the Company may terminate service immediately and without notice. The backflow-prevention assembly shall be repaired or replaced by the customer and retested.
8. In the event the backflow-prevention assembly does not function properly or fails any test, or in the event that a customer fails to comply with the testing requirement, and A.A.C. R14-2-410.B.1.a. is **not** applicable, the backflow-prevention assembly shall be repaired or replaced within fourteen (14) days of the initial discovery of the deficiency in the assembly or its function. Failure to remedy the deficiency or dysfunction of the assembly, or failure to retest, shall be grounds for termination of water service in accordance with A.A.C. R14-2-410.

****FOR OFFICIAL USE ONLY****

Effective Date: _____