



PINE VALLEY WATER CO

480 Raintree Road Sedona Arizona
Phone: (928) 284-9311 Email: lllinaz@earthlink.net



0000172857

ORIGINAL

Docket Control Center
Arizona Corporation Commission
1200 West Washington Street
Phoenix, Arizona 85007

August 19, 2016

Subject: Docket No. W-02181A-15-0216

Decision No. 75554

Enclosed please find the original and 13 copies of this filing for Pine Valley Water Company to show we have complied with lines 25 through 28 of page 17 of the above decision regarding correcting substandard electrical installations at Pine Valley Water Company booster building and well pump area. This is to be filed with docket control in compliance of rate increase. If you have any questions please feel free to contact me, thank you.



Sincerely,

Lisa Wischmeier
Secretary, Pine Valley Water Company

Arizona Corporation Commission
DOCKETED
AUG 25 2016

DOCKETED BY


RECEIVED
AZ CORP COMMISSION
DOCKET CONTROL
2016 AUG 25 A 10:31



Docket No. W-02181A-15-0216 Decision No. 75554
Subject: Compliance with lines 25 through 28 of page 17 correcting substandard electrical installations at Pine Valley Water Company booster building and well pump area

The above photos show the corrections to the substandard electrical installations noted in the Booster Building. The photo on the left with the red arrows indicate the 2 junction boxes noted that had exposed wiring (please note the lower arrow shows bare wire but it was not until I began the correction process that I realized I should take before pictures, the wires were wire nuted but were not enclosed).

The photo on the right with the green arrows shows these connections after having been properly enclosed.



Docket No. W-02181A-15-0216 Decision No. 75554
Subject: Compliance with lines 25 through 28 of page 17 correcting
substandard electrical installations at Pine Valley Water Company
booster building and well pump area

These photos show that the substandard electrical installations have been corrected in the well pump area. Photo 1 shows the overall area that was in question after corrections; photo 3 is the old electrical panel system that has been removed. The old system was replaced by all the updated electrical equipment and panels being placed on the protected back of the pump house/booster building as shown in picture 4. Picture 2 is a closer picture of the ground from picture 1 to show all old wiring that may have been unsightly or been a trip hazard has been removed.