

ORIGINAL

Desert Mountain Analytical Services,



0000046178

March 31, 2006

Arizona Corporation Commission
Docket Control
1200 West Washington Street
Phoenix, AZ 85007-2927

AZ CORP COMMISSION
DOCUMENT CONTROL

2006 MAR 31 P 1:38

RECEIVED

RE: Docket No. W-02089A-06-0041
Bradshaw Mountain View Water Company

Dear Sir or Madam:

This letter is written in response to Staff's Letter of Deficiency dated February 23, 2006, regarding the above stated matter. Staff cited two deficiency items to which we are responding:

1. Supporting documents for plant additions for the years 1987 through 1996 are not available. Bradshaw Mountain View Water Company ("Bradshaw" or "Company") has provided copies of all invoices they have available for plant additions. Due to the age of some of the additions, the Company is not able to locate the invoices.
2. Bradshaw has obtained a corrected Drinking Water Compliance Status Report from the Arizona Department of Environmental Quality, dated 03/29/2006, which reflects the company is in compliance with current standards. A copy is attached to this letter.

Additionally, Bradshaw is providing responses to seven questions emailed to Tim Kylo, owner of the Company, by Staff Engineer Dorothy Haines. Although these items were not included on the February 23, 2006 Letter of Deficiency, Bradshaw is able to provide responses at this time:

1. The response to question 2 above will satisfy this question. There was an error regarding the MAP program that has now been corrected, and proof Bradshaw is providing water that meets standards is attached.
2. Water loss in the last three months of the test year was 15% (up from the average loss of below 10%) due in part to the Mayer Fire Department testing fire hydrants and flushing mains after repair work. These activities amounted to approximately 100,000 gallons per month of usage.

PO Box 51628 Ahwatukee, AZ 85076-1628
Phone: 480.961.5484 - Fax: 480.961.5488
Email: sonncpa@qwest.net

3. Bradshaw's arsenic testing is done by MAP (Monitoring Assistance Program). The last test was conducted on 03/02/04, and the results were 0.0032 mg/l, which is under the new MCL.
4. The Company ran out of water during the summer of 2004 due to the collapse of one of the wells. The well was re-drilled and a new casing was installed. However, to keep up with peak summer demands, the Company plans to add storage tanks and a new booster pump station at an estimated cost of \$65,000.
5. The total amount of purchased was insignificant (approximately 15,000 gallons) and was not included in pumped water totals on the water usage data sheet.
6. Although ADEQ's report shows that there are seven wells in the system, Bradshaw has only three wells that are currently in service. The other wells have either been abandoned or are not in service at this time.
7. Question 7 regarding purchased water appears to be substantially the same as Question 5.

Sincerely,

A handwritten signature in cursive script that reads "Sonn S Rowell". The signature is written in black ink and is positioned above the typed name.

Sonn S Rowell
Certified Public Accountant
for Bradshaw Mountain View Water Company
enc

Arizona Department of Environmental Quality
Water Quality Compliance Assurance Unit
1110 W. Washington Street, 5415B-1
Phoenix, AZ 85007

Drinking Water Compliance Status Report

Public Water System Name: Bradshaw MT. View Water Co.

Public Water System ID #: 13-062

Public Water System Type: CO Non-transient Non-community Transient Non-community

Overall Compliance Status: No Major Deficiencies Major Deficiencies

Monitoring and Reporting Status: No Major Deficiencies Major Deficiencies

Comments:

Operation and Maintenance Status: No Major Deficiencies Major Deficiencies

Comments:

Major unresolved/ongoing operation and maintenance deficiencies:

- | | |
|---|---|
| <input type="checkbox"/> unable to maintain 20psi | <input type="checkbox"/> inadequate storage |
| <input type="checkbox"/> cross connection/backflow problems | <input type="checkbox"/> surface water treatment rule |
| <input type="checkbox"/> treatment deficiencies | <input type="checkbox"/> approval of construction |
| <input type="checkbox"/> certified operator | <input type="checkbox"/> other |

Date of last inspection / sanitary survey: 7-7-04

Administrative Orders:

Is an ADEQ administrative order in effect? Yes No

Comments:

System information:

Number of Points of Entry 3 Number of Sources 7 Population Served 1100

Service Connections 561 Initial Monitoring Year 1995 Initial MAP Year 2001

Evaluation completed by: **Jim Puckett**

Phone: 602-771-4649 **Date:** 3-29-06

Based upon data submitted by the water system, ADEQ has determined that this system is currently delivering water that meets water quality standards required by Arizona Administrative Code, Title 18, Chapter 4. This compliance status report does not guarantee the water quality for this system in the future. This compliance status report does not reflect the status of any other water system owned by this utility company.