


ORIGINAL



RECEIVED

2007 JUN 19 A 11:42

AZ CORP COMMISSION
DOCKET CONTROL



CAMELOT HOMES
Aspire Higher™

4700

Chairman Mike Gleason
Commissioner Kristin Mayes
Commissioner William Mundell
Commissioner Jeff Hatch-Miller
Commissioner Gary Pierce
Arizona Corporation Commission
1200 W. Washington - 2nd Floor
Phoenix, Arizona 85007

SW-01428A-06-0444

Arizona Corporation Commission
DOCKETED

JUN 19 2007

June 11, 2007

DOCKETED BY	nr
-------------	----

Dear Commissioners,

I am writing to seek your help in resolving a serious persistent odor problem emanating from LPSLO's wastewater treatment plant at 143rd Ave & McDowell Rd in Goodyear. We're one of numerous neighbors in the area of the plant who have experienced regular odor emissions from this plant for the past several years.

We've communicated with plant management on numerous occasions to report concerns and seek updates on planned corrective measures. Plant officials have acknowledged issues with the plant, and have indicated that fixes have been developed. The most recent fix was implemented in December 2001 and was promised to eliminate 98% of noticeable odor emissions. A noticeable improvement did result for about 3 months before the odor returned. While management again acknowledges they are working on correcting the problem, we feel we have reached the end of our reasonable patience and believe strong measures need to be imposed to fix the problem.

It's apparent to us that while management has assessed the problems with their plant, their efforts have failed to truly identify the source, scope or extent of their problems or they have failed to effectively implement the proper corrective measures. They indicate that they have a "phase 2" corrective measure scheduled for the 3rd Quarter of this year, however we seriously doubt this will have any impact based on their previous failed attempts to correct the problem.

In the meantime, we wait and see our business, our customers and our neighborhood suffer with no realistic solution in the works. Please exercise the regulatory control that you have over their operating license to force them to commit more resources to correct this problem quickly!

Sincerely,
Thomas Kirk

Chief Operating Officer