

ORIGINAL



0000078539

SALLQUIST, DRUMMOND & O'CONNOR, P.C.

ATTORNEYS AT LAW  
TEMPE OFFICE

4500 S. LAKESHORE DRIVE  
SUITE 339

TEMPE, ARIZONA 85282

RECEIVED

NOV -9 P 3:41

AZ CORP COMMISSION  
DOCKET CONTROL

PHONE (480) 839-5202  
FACSIMILE (480) 345-0412  
E-MAIL [dick@sd-law.com](mailto:dick@sd-law.com)

RICHARD L. SALLQUIST

November 8, 2007

**HAND DELIVERY**

Blessing Chukwu  
Arizona Corporation Commission  
Utilities Division  
1200 W. Washington  
Phoenix, AZ 85007

Re: Keaton Development Company-Docket No. W-02169A-07-0098; Supplemental Data

Dear Blessing:

On September 26, 2007 we provided an ADEQ Compliance Status Report that indicated there were "Major Deficiencies" on the Keaton system. We indicated that those had been resolved, but the ADEQ paperwork had not yet acknowledged that fact. As our correspondence stated, the Certified Operator did immediately contact ADEQ at that time. Attached hereto is the new Report dated November 8, 2007, a full 43 day turnaround.

In the event you have any questions regarding these matters, please do not hesitate to call.

Sincerely,

Richard L. Sallquist

Enclosure

cc: Docket Control (15 copies)  
Bill Scott

Arizona Corporation Commission

DOCKETED

NOV 09 2007

DOCKETED BY

**Arizona Department of Environmental Quality**  
Drinking Water Monitoring and Protection Unit  
1110 W. Washington Street, 5415B-1  
Phoenix, AZ 85007

**Drinking Water Compliance Status Report**

Public Water System Name: Keaton Development Co.

Public Water System ID #: 15-029

Public Water System Type:  Community  Non-transient Non-community  Transient Non-community

Overall Compliance Status:  No Major Deficiencies  Major Deficiencies

Monitoring and Reporting Status:  No Major Deficiencies  Major Deficiencies

Comments:

The ADEQ data base does not show that the required 2007 Disinfection Byproducts (DBP) analysis have been done for this water system during the months of warmest water temperature (June, July, August, or September) in 2007. While this does not constitute a major deficiency according to ADEQ policy and procedures, this is a violation of the Arizona Administrative Code, Title 18, Chapter 4. If the 2010 DBP samples are not taken during the months of warmest water temperature, this system will have a major DBP monitoring deficiency for 2007 and 2010.

Operation and Maintenance Status:  No Major Deficiencies  Major Deficiencies

Comments:

Major unresolved/ongoing operation and maintenance deficiencies:

- unable to maintain 20psi
- cross connection/backflow problems
- treatment deficiencies
- certified operator
- inadequate storage
- surface water treatment rule
- approval of construction
- other

Date of last inspection / sanitary survey: 3-6-06

Administrative Orders:

Is an ADEQ administrative order in effect?  Yes  No

Comments:

System information:

Number of Entry Points to the Distribution System 1 Number of Sources 2

Population Served 1200 Service Connections 496 Initial Monitoring Year 1995

Evaluation completed by: Jim Puckett, Environmental Health Specialist II

Phone: 602-771-4649 Date: 11-8-07

Based upon data submitted by the water system, ADEQ has determined that this system is currently delivering water that meets water quality standards required by Arizona Administrative Code, Title 18, Chapter 4. This compliance status report does not guarantee the water quality for this system in the future. This compliance status report does not reflect the status of any other water system owned by this utility company.