

**ORIGINAL**

LAW OFFICES

**MARTIN & BELL, L.L.C.**  
365 EAST CORONADO ROAD  
SUITE 200  
PHOENIX, ARIZONA 85004



0000093435

50

**DOUGLAS G. MARTIN**  
CERTIFIED SPECIALIST REAL ESTATE LAW  
ARIZONA BOARD OF LEGAL  
SPECIALIZATION  
DMARTIN@MARTIN-BELL.COM

**LEONARD BELL**  
ATTORNEY  
LBELL@MARTIN-BELL.COM

**ADAM BREEZE**  
ATTORNEY  
ABREEZE@MARTIN-BELL.COM

TELEPHONE  
(602) 230-0030  
TELECOPIER  
(602) 604-0004

www.martin-bell.com

**RECEIVED**

2009 JAN 30 P 4: 47

January 30, 2009  
**AZ CORP COMMISSION  
DOCKET CONTROL**

**LEGAL ASSISTANTS**  
**Rachel D. Grayczyk**  
RACHEL@MARTIN-BELL.COM

**Lillian C. Kirby**  
LKIRBY@MARTIN-BELL.COM

**Megan R. Bray**  
MBRAY@MARTIN-BELL.COM

**Norman B. Martin, m.p.a.**  
NBMBMW@AOL.COM

Arizona Corporation Commission  
Docket Control  
1200 W. Washington  
Phoenix, AZ 85007

Attn: Docket Control

Please accept the following information for compliance with Decision No. 70102, Dells Water Company Permanent Rate Increase.

\* "that the Company monitor the system and submit the gallons pumped and sold to determine the actual water loss for one full year. The results of this monitoring and reporting should be docketed as a compliance item in this case within 13 months of the effective date of this Decision. If the reported water loss for the period is greater than 10 percent, the Company shall prepare a report containing a detailed analysis and plan to reduce water loss to 10 percent or less. If the Company believes it is not cost effective to reduce water loss to less than 10 percent, it should submit a detailed cost benefit analysis to support its opinion. In no case shall the Company allow water loss to be greater than 15 percent. The water loss reduction report or the detailed analysis, whichever is submitted, shall be docketed as a compliance item in this docket within 13 months of the effective date of this Decision;"

The Company sold a total of 8,307,624 for the calendar year 2008. There are two wells serving the Dells Water Company service area. Well 55-802749 pumped 3,070, 174 gallons between December 28, 2007 and January 9, 2009 when the well meter was read. It is uncertain as to how much the second well 55-802748 pumped. Last summer, it was discovered that the meter on the well was defective and it was replaced. Since that time, the well has pumped 1,531,790 gallons.

The Company will again monitor the water usage during 2009 and will compare water sold to water pumped. If there is any water loss exceeding 10 percent, the Company will prepare a detailed plan to reduce water loss to less than 10 percent.

Please let me know if there are any questions with this submittal.

Cordially,

Jim West

Arizona Corporation Commission  
**DOCKETED**

JAN 30 2009

DOCKETED BY