

ORIGINAL

Sheila Stoelle



0000109377

E-01575A-09-0453
E-01575A-08-0328

From: swolf24025@aol.com
Sent: Friday, March 26, 2010 8:05 AM
To: Mayes-WebEmail
Subject: sulphur electric lines

Please put this into the docket...

I have two big concerning the route line:

1. They are placing this in area that is prone to fires...we experience fires due to the combination of drought and grasses. Where they plan to place the line, it would be impossible to get to should a fire occur and knock out power....it makes alot more sense to put this on the existing route
2. The route is in a flood plain.....I've seen rushing water come down in the monsoon season....when lines are interrupted because of thunderstorms, they will not be able to get to them for repairs. When the water subsides the mud will sink any truck going back there.....The washes are hundreds of feet wide....the professionals from Mass. have no clue about how dangerous they can be.

The route needs to go on 83

sandy wolf

Sandra S. Wolf ChFC, CSA
Long Term Care Specialist
www.swolfinsurance.com
520-455-9241

Arizona Corporation Commission

DOCKETED

MAR 26 2010

DOCKETED BY	<i>MS</i>
-------------	-----------

AZ CORP COMMISSION
DOCKET CONTROL

2010 MAR 26 P 3:57

RECEIVED