

ORIGINAL



0000144531

SHADLE & WALSMAS, PLC

STEPHEN P. SHADLE *
PAMELA WALSMAS **

ATTORNEYS AT LAW
833 E. Plaza Circle, Suite 200
Yuma, Arizona 85365-2017
Telephone (928) 783-8321
Facsimile (928) 783-8321

RECEIVED
AZ CORP COMMISSION
DOCKET CONTROL

*Also Admitted in California and Iowa
**Also Admitted in Missouri

April 23 2013 APR 24 AM 10 21

Docket Control
Arizona Corporation Commission
1200 W. Washington Street
Phoenix, Arizona 85007

RE: DOCKET NO: W-02059A-11-0172 & W-20801A-11-0172

Enclosed herein are the originals and thirteen (13) copies of each of the following items which are being sent for filing to demonstrate compliance with Decision No. 73785 dated March 21, 2013:

1. Cover letter and Tariff Schedule for Curtailment Plan.
2. Cover letter and Cross-Connection or Backflow Tariff.

Thank you for your assistance in this regard and please call if you have any questions regarding the enclosed filings.

Very truly yours,

Pamela Walsma

PW:jw
Enclosures

Arizona Corporation Commission
DOCKETED

APR 24 2013

DOCKETED BY	JM
-------------	----

***Desert Valencia Water, Inc.
2000 Forest Hills Road
Prescott, AZ 86303***

April 18, 2013

Docket Control
Arizona Corporation Commission
1200 West Washington Street
Phoenix, Arizona 85007

RE: DOCKET NO: W-02059A-11-0172 & W-20801A-11-0172

Attached is a Cross-Connection Tariff being filed by Desert Valencia Water, Inc. for approval. The purpose of this tariff is to protect Desert Valencia Water, Inc. from the possibility of contamination caused by backflow of contaminants that may be present on the customer's premises.

This Tariff is being filed as a compliance item pursuant to Decision No. 73785 dated March 21, 2013.



Scott Wootton, President

CROSS-CONNECTION OR BACKFLOW TARIFF

PURPOSE:

The purpose of this tariff is to protect Desert Valencia Water, Inc. ("Company") water from the possibility of contamination caused by the backflow of contaminants that may be present on the customer's premises by requiring the installation and periodic testing of backflow-prevention assemblies pursuant to the provisions of the Arizona Administrative Code ("A.A.C.") R14-2-405.B.6 and A.A.C. R18-4-215.

REQUIREMENTS:

In compliance with the Rules of the Arizona Corporation Commission ("Commission") and the Arizona Department of Environmental Quality ("ADEQ"), specifically A.A.C. R14-2-405.B.6 and A.A.C. R18-4-215 relating to backflow prevention:

1. The Company may require a customer to pay for and to have installed a backflow-prevention assembly if A.A.C. R18-4-215.B or C applies.
2. A backflow-prevention assembly required to be installed by the customer under Paragraph 1 of this tariff shall comply with the requirements set forth in A.A.C. R18-4-215.D and E.
3. Subject to the provisions of A.A.C. R14-2-407 and 410, and in accordance with Paragraphs 1 and 7 of this tariff, the Company may terminate service or may deny service to a customer who fails to install a backflow-prevention assembly as required by this tariff
4. The Company shall give any existing customer who is required to install a backflow-prevention assembly written notice of said requirement. If A.A.C. R14-2-410.B.1.a. is not applicable, the customer shall be given thirty (30) days from the time such written notice is received in which to comply with this notice. If the customer can show good cause as to why he cannot install the backflow-prevention assembly within thirty (30) days, the Company or Commission Staff may suspend this requirement for a reasonable period of time.

****FOR OFFICIAL USE ONLY****

Effective Date: _____

5. Testing shall be in conformance with the requirements of A.A.C. R18-4-215.F. The Company may require the customer to pay to have the backflow-prevention assembly tested as long as the Company does not require an unreasonable number of tests.
6. The customer shall provide the Company with records of installation and testing. For each backflow-prevention assembly, these records shall include:
 - a. assembly identification number and description;
 - b. location
 - c. date(s) of test(s);
 - d. description of repairs and recommendations for repairs made by tester;
and
 - e. the tester's name and certificate number.
7. In the event the backflow-prevention assembly does not function properly or fails any test, and an obvious hazard as contemplated under A.A.C. R14-2-410.B.1.a. exists, the Company may terminate service immediately and without notice. The backflow-prevention assembly shall be repaired or replaced by the customer and retested.
8. In the event the backflow-prevention assembly does not function properly or fails any test, or in the event that a customer fails to comply with the testing requirement, and A.A.C. R14-2-410.B.1.a. is not applicable, the backflow-prevention assembly shall be repaired or replaced within fourteen (14) days of the initial discovery of the deficiency in the assembly or its function. Failure to remedy the deficiency or dysfunction of the assembly, or failure to retest, shall be grounds for termination of water service in accordance with A.A.C. R14-2-410.

****FOR OFFICIAL USE ONLY****

Effective Date: _____