

ORIGINAL NEW APPLICATION



0000154058

LAWRENCE V. ROBERTSON, JR.
ATTORNEY AT LAW

P. O. Box 1448
TUBAC, ARIZONA 85646

(520) 398-0411
FAX: (520) 398-0412
EMAIL: TUBACLAWYER@AOL.COM

OF COUNSEL TO
MUNGER CHADWICK
ATTORNEYS AT LAW

RECEIVED

2014 AUG 29 A 11:22

ADMITTED TO PRACTICE IN:
ARIZONA, COLORADO, MONTANA,
NEVADA, TEXAS, WYOMING,
DISTRICT OF COLUMBIA

DOCKET CONTROL

August 26, 2014

Docket Control
Arizona Corporation Commission
1200 West Washington
Phoenix, Arizona 85007

WS-04245A-14-0316

Arizona Corporation Commission
DOCKETED

AUG 29 2014

DOCKETED BY

Re: Red Rock Utilities, L.L.C.
Docket No. WS-04245A-14-____
Updated Cross Connection or Backflow Tariff

To Whom It May Concern:

Enclosed for filing are fourteen (14) copies of an updated Cross Connection or Backflow Tariff for Red Rock Utilities, L.L.C. ("Red Rock"). The revisions reflected in the attached document are intended to (i) incorporate changes made by the Arizona Department of Environmental Quality with respect to the content of such documents since Red Rock's existing tariff on the subject was filed with the Commission, and (ii) conform the tariff to the Commission's current template upon the subject.

Thank you for your assistance in processing the attached updated Cross Connection or Backflow Tariff. Please let me know if you have any questions regarding the above or the attached.

Sincerely,

Lawrence V. Robertson, Jr.

cc: Red Rock Utilities, L.L.C.

c:\users\angela\documents\larry\diamond ventures\red rock utilities\cross-ncnctn bckflw trff\dckt cntrl ltr. 8-26-14.doc

PHOENIX OFFICE: 2398 E. CAMELBACK RD., STE 240, PHOENIX AZ 85016 PH: (602) 358-7348 FAX: (620) 441-2779

TUCSON OFFICE: 333 N. WILMOT RD, STE 300, TUCSON AZ 85711 PH: (520) 721-1900 FAX: (520) 747-1550

CROSS-CONNECTION OR BACKFLOW TARIFF

PURPOSE:

The purpose of this tariff is to protect Red Rock Utilities, LLC (“Company”) water from the possibility of contamination caused by the backflow of contaminants that may be present on the customer’s premises by requiring the installation and periodic testing of backflow-prevention assemblies pursuant to the provisions of the Arizona Administrative Code (“A.A.C.”) R14-2-405.B.6 and A.A.C. R18-4-115.

REQUIREMENTS:

In compliance with the Rules of the Arizona Corporation Commission (“Commission”) and the Arizona Department of Environmental Quality (“ADEQ”), specifically A.A.C. R14-2-405.B.6 and A.A.C. R18-4-115 relating to backflow prevention:

1. The Company may require a customer to pay for and to have installed a backflow-prevention assembly if A.A.C. R18-4-115.B or C applies.
2. A backflow-prevention assembly required to be installed by the customer under Paragraph 1 of this tariff shall comply with the requirements set forth in A.A.C. R18-4-115.D and E.
3. Subject to the provisions of A.A.C. R14-2-407 and 410, and in accordance with Paragraphs 1 and 7 of this tariff, the Company may terminate service or may deny service to a customer who fails to install a backflow-prevention assembly as required by this tariff
4. The Company shall give any existing customer who is required to install a backflow-prevention assembly written notice of said requirement. If A.A.C. R14-2-410.B.1.a. is **not** applicable, the customer shall be given thirty (30) days from the time such written notice is received in which to comply with this notice. If the customer can show good cause as to why he cannot install the device within thirty (30) days, the Company or Commission Staff may suspend this requirement for a reasonable period of time.

****FOR OFFICIAL USE ONLY****

Effective Date: _____

5. Testing shall be in conformance with the requirements of A.A.C. R18-4-115.F. The Company may require the customer to pay to have the backflow-prevention assembly tested as long as the Company does not require an unreasonable number of tests.
6. The customer shall provide the Company with records of installation and testing. For each backflow-prevention assembly, these records shall include:
 - a. assembly identification number and description;
 - b. location
 - c. date(s) of test(s);
 - d. description of repairs and recommendations for repairs made by tester; and
 - e. the tester's name and certificate number.
7. In the event the backflow-prevention assembly does not function properly or fails any test, and an obvious hazard as contemplated under A.A.C. R14-2-410.B.1.a. exists, the Company may terminate service immediately and without notice. The backflow-prevention assembly shall be repaired or replaced by the customer and retested.
8. In the event the backflow-prevention assembly does not function properly or fails any test, or in the event that a customer fails to comply with the testing requirement, and A.A.C. R14-2-410.B.1.a. is **not** applicable, the backflow-prevention assembly shall be repaired or replaced within fourteen (14) days of the initial discovery of the deficiency in the assembly or its function. Failure to remedy the deficiency or dysfunction of the assembly, or failure to retest, shall be grounds for termination of water service in accordance with A.A.C. R14-2-410.

****FOR OFFICIAL USE ONLY****

Effective Date: _____