

ORIGINAL



0000017769

LAW OFFICES

FENNEMORE CRAIG

A PROFESSIONAL CORPORATION

50

PATRICK J. BLACK

Direct Phone: (602) 916-5400

Direct Fax: (602) 916-5600

pblack@fclaw.com

OFFICES IN:
PHOENIX, TUCSON,
NOGALES, AZ; LINCOLN, NE

3003 NORTH CENTRAL AVENUE
SUITE 2600
PHOENIX, ARIZONA 85012-2913
PHONE: (602) 916-5000
FAX: (602) 916-5999

April 28, 2005

Mr. Brian Bozzo, Compliance Manager
Utilities Division
Arizona Corporation Commission
1200 W. Washington St.
Phoenix, Arizona 85007

Arizona Corporation Commission

DOCKETED

APR 28 2005

DOCKETED BY	<i>KB</i>
-------------	-----------

Re: Johnson Utilities Company- Compliance with Decision Nos. 64062, 65840
ACC Docket Nos.: W-02234A-00-0371; WS-02987A-99-0583;
WS-02987A-00-0618; W-02859A-00-0774; W-01395A-00-0784

Dear Mr. Bozzo:

Pursuant to Commission Decision No. 64062 (October 4, 2001), as amended by Decision No. 65840 (April 22, 2003), Johnson Utilities Company ("Johnson Utilities") hereby submits this compliance filing in accordance with the Commission's orders in the above-referenced matter. Enclosed please find Arizona Department of Environmental Quality ("ADEQ") Drinking Water Compliance Status Reports for Johnson Utilities' three water systems.

- 1. PWS ID # - 11-116 Sun Valley
- 2. PWS ID # - 11-128 Johnson Utilities
- 3. PWS ID # - 11-245 Wildhorse

...
...
...

AZ CORP COMMISSION
DOCUMENT CONTROL

2005 APR 28 P 4: 35

RECEIVED

FENNEMORE CRAIG

Mr. Brian Bozzo, Compliance Manager

April 28, 2005

Page 2

Johnson Utilities will be filing documentation of compliance with ADEQ regulations for its **wastewater** system under separate cover. Based on the enclosed ADEQ reports, Johnson Utilities is currently in compliance with all ADEQ regulations for its water systems. Should you have any questions, please do not hesitate to contact me. Thank you for your time and consideration in this matter.

Very truly yours,



Patrick J. Black

Enclosures

cc: Brian Tompsett, Johnson Utilities Company (w/enc.)
Ernest Johnson, Director – Utilities Division (w/enc.)
Docket Control (w/enc.)

SUN VALLEY

Arizona Department of Environmental Quality
Water Quality Compliance Assurance Unit
1110 W. Washington Street, 5415B-1
Phoenix, AZ 85007

Drinking Water Compliance Status Report

Public Water System Name: Johnson Utilities – Sun Valley

Public Water System ID #: 11-116

Public Water System Type: CO Non-transient Non-community Transient Non-community

Overall Compliance Status: No Major Deficiencies Major Deficiencies

Monitoring and Reporting Status: No Major Deficiencies Major Deficiencies

Comments:

Operation and Maintenance Status: No Major Deficiencies Major Deficiencies

Comments:

Major unresolved/ongoing operation and maintenance deficiencies:

- | | |
|---|---|
| <input type="checkbox"/> unable to maintain 20psi | <input type="checkbox"/> inadequate storage |
| <input type="checkbox"/> cross connection/backflow problems | <input type="checkbox"/> surface water treatment rule |
| <input type="checkbox"/> treatment deficiencies | <input type="checkbox"/> approval of construction |
| <input type="checkbox"/> certified operator | <input type="checkbox"/> other |

Date of last inspection / sanitary survey: 12-30-03

Administrative Orders:

Is an ADEQ administrative order in effect? Yes No

Comments:

System information:

Number of Points of Entry 1 Number of Sources 1 Population Served 77

Service Connections 37 Initial Monitoring Year 1996 Initial MAP Year 2002

Evaluation completed by: Jim Puckett

Phone: 602-771-4649 **Date:** 4-28-05

Based upon data submitted by the water system, ADEQ has determined that this system is currently delivering water that meets water quality standards required by Arizona Administrative Code, Title 18, Chapter 4. This compliance status report does not guarantee the water quality for this system in the future. This compliance status report does not reflect the status of any other water system owned by this utility company.

JOHNSON UTILITIES

Arizona Department of Environmental Quality
Water Quality Compliance Assurance Unit
1110 W. Washington Street, 5415B-1
Phoenix, AZ 85007

Drinking Water Compliance Status Report

Public Water System Name: Johnson Utilities

Public Water System ID #: 11-128

Public Water System Type: CO Non-transient Non-community Transient Non-community

Overall Compliance Status: No Major Deficiencies Major Deficiencies

Monitoring and Reporting Status: No Major Deficiencies Major Deficiencies
Comments:

Operation and Maintenance Status: No Major Deficiencies Major Deficiencies
Comments:

Major unresolved/ongoing operation and maintenance deficiencies:

- | | |
|---|---|
| <input type="checkbox"/> unable to maintain 20psi | <input type="checkbox"/> inadequate storage |
| <input type="checkbox"/> cross connection/backflow problems | <input type="checkbox"/> surface water treatment rule |
| <input type="checkbox"/> treatment deficiencies | <input type="checkbox"/> approval of construction |
| <input type="checkbox"/> certified operator | <input type="checkbox"/> other |

Date of last inspection / sanitary survey: 1-15-05

Administrative Orders:
Is an ADEQ administrative order in effect? Yes No
Comments:

System information:

Number of Points of Entry 3 Number of Sources 6 Population Served 24572

Service Connections 8776 Initial Monitoring Year 2000 Initial MAP Year 2000

Evaluation completed by: Jim Puckett

Phone: 602-771-4649 **Date:** 2-9-05

Based upon data submitted by the water system, ADEQ has determined that this system is currently delivering water that meets water quality standards required by Arizona Administrative Code, Title 18, Chapter 4. This compliance status report does not guarantee the water quality for this system in the future. This compliance status report does not reflect the status of any other water system owned by this utility company.

WILDHORSE

Arizona Department of Environmental Quality
Water Quality Compliance Assurance Unit
1110 W. Washington Street, 5415B-1
Phoenix, AZ 85007

Drinking Water Compliance Status Report

Public Water System Name: Wildhorse

Public Water System ID #: 11-245

Public Water System Type: CO Non-transient Non-community Transient Non-community

Overall Compliance Status: No Major Deficiencies Major Deficiencies

Monitoring and Reporting Status: No Major Deficiencies Major Deficiencies

Comments:

Operation and Maintenance Status: No Major Deficiencies Major Deficiencies

Comments:

Major unresolved/ongoing operation and maintenance deficiencies:

- | | |
|---|---|
| <input type="checkbox"/> unable to maintain 20psi | <input type="checkbox"/> inadequate storage |
| <input type="checkbox"/> cross connection/backflow problems | <input type="checkbox"/> surface water treatment rule |
| <input type="checkbox"/> treatment deficiencies | <input type="checkbox"/> approval of construction |
| <input type="checkbox"/> certified operator | <input type="checkbox"/> other |

Date of last inspection / sanitary survey: none

Administrative Orders:

Is an ADEQ administrative order in effect? Yes No

Comments:

System information:

Number of Points of Entry 1 Number of Sources 1 Population Served 60

Service Connections 21 Initial Monitoring Year 2006 Initial MAP Year 2006

Evaluation completed by: Jim Puckett

Phone: 602-771-4649 **Date:** 4-27-05

Based upon data submitted by the water system, ADEQ has determine that this system is currently delivering water that meets water quality standards required by Arizona Administrative Code, Title 18, Chapter 4. This compliance status report does not guarantee the water quality for this system in the future. This compliance status report does not reflect the status of any other water system owned by this utility company.