

ORIGINAL



0000025338

RECEIVED

**COMPLIANCE
MEMORANDUM**

2002 JAN -2 A 11:34

AZ CORP COMMISSION
DOCUMENT CONTROL

TO: Docket Control Center
FROM: Patrick C. Williams 
Manager, Compliance and Enforcement
Utilities Division
DATE: January 02, 2002

This Memorandum to the Docket will certify that compliance, as described below, has been met for the referenced utility.

UTILITY: Francesca Water Company, Inc.

DOCKET NO. W-02838A-00-0684 **DECISION NO.** 63660
ET. AL.

COMPLIANCE ACTION:


Rates shall be interim and subject to refund until the Company files documentation from the ADEQ that the Amber Ann system is providing water that meets the quality standards of the Safe Drinking Water Act and files documentation from the ADEQ by December 31, 2001.

DUE DATE: 12/31/2001 **DATE COMPLIED:** 12/31/2001

Arizona Corporation Commission


DOCKETED

JAN 02 2002

DOCKETED BY	
-------------	---

DOCKET # W-02838 A-00-0684

DECISION 63660



FAX TRANSMISSION

Arizona Department of Environmental Quality
 Water Quality Division
 Water Quality Compliance Section
 Drinking Water Compliance and Enforcement Unit
 3033 North Central Avenue ~ MO - 501B
 Phoenix, AZ 85012-2809

ADEQ Toll Free Within Arizona (800) 234-5677 ext. 4624

General Information (602) 207-2300

FAX (602) 207-4505

To: John Chelus

FAX #: 542-2129

Phone #: _____

From: Melanie Diroll

Phone #: (602) 207-4530

Comments: _____

TOTAL PAGES INCLUDING THIS: 2

**Arizona Department of Environmental Quality
Drinking Water Compliance Enforcement Unit
3033 N. Central Avenue, M0501B**

DOCKET NO. W-02838A Phoenix, AZ 85012

DECISION NO. 63660 -00-0684

Compliance Status Report

PWS Name: Francesca Water - Amber Ann

PWS ID #: 10-317

Compliance Status: No Major Deficiencies Major Deficiencies

Comments:

****This a new regulated public water system. This status report is based upon source approval analytical results taken at the well. This water system is currently working with Pima County DEQ to resolve storage deficiencies.****

Date of last inspection / sanitary survey: 10/31/01

Major Operation and Maintenance Deficiencies cited during inspection:

- None
- unable to maintain 20psi
- inadequate storage
- cross connection/backflow problems
- surface water treatment rule
- treatment deficiencies
- approval of construction
- certified operator

Administrative Orders:

Is ADEQ administrative order in effect? Yes No

Is US EPA administrative order in effect? Yes No

Comments:

System information:

Number of Points of Entry 1 Population Served 108
Initial Monitoring Year 2002 MAP year 2002

DWCE Evaluation completed by: Melanie Diroll

Phone: 602-207-4530 **Date:** Dec. 31, 2001

Based on data submitted by the water system, ADEQ has determined that this system is currently delivering water that meets water quality standards required by Arizona Administrative Code, Title 18, Chapter 4. This compliance status report does not guarantee the water quality for this system in the future. This compliance status report does not reflect the status of any other water system owned by this utility company.