

ORIGINAL



**COMPLIANCE
MEMORANDUM**

2002 FEB -6 A 10: 52

AZ CORP COMMISSION
DOCUMENT CONTROL

TO: Docket Control Center
FROM: Patrick C. Williams *PCW*
Manager, Compliance and Enforcement
Utilities Division
DATE: February 06, 2002

This Memorandum to the Docket will certify that compliance, as described below, has been met for the referenced utility.

UTILITY: Mount Tipton Water Company, Inc.

DOCKET NO. W-02105A-01-0556 **DECISION NO.** 64287

COMPLIANCE ACTION:


Mount Tipton Water Company, Inc. shall not interconnect the Mount Tipton Water Company, Inc. and Dolan Springs Water Company, Inc. systems until such time that it has filed documentation with the Commission's Utilities Division Director demonstrating that both of the present water systems are delivering water that meets the water quality standards promulgated by the Arizona Department of Environmental Quality.

DUE DATE: **DATE COMPLIED:** 02/06/2002

Arizona Corporation Commission
DOCKETED
FEB 06 2002

DOCKETED BY *PCW*

MEMORANDUM



TO: Patrick C. Williams
Manager, Compliance and Enforcement
Utilities Division

FROM: Marlin Scott, Jr. *MSJ*
Utilities Engineer
Utilities Division

DATE: February 6, 2002

RE: MOUNT TIPTON WATER COMPANY
DOCKET NO. W-01977A-01-0557 et.al. (Sale/Transfer/Financing)
COMPLIANCE WITH DECISION NO. 64287

Mount Tipton Water Company (Company) was granted approval to purchase Dolan Springs Water Company in Decision No. 64287, dated December 31, 2001. In that Decision, one of the Orders was,

“[t]hat Mount Tipton Water Company, Inc. shall not interconnect the Mount Tipton Water Company, Inc. and Dolan Springs Water Company, Inc., systems until such time that it has filed documentation with the Commission’s Utilities Division Director demonstrating that both of the present water systems are delivering water that meets the water quality standards promulgated by the Arizona Department of Environmental Quality.”

On February 6, 2002, Staff Engineering received Dolan Springs’ ADEQ documentation. Staff also received Mount Tipton’s ADEQ documentation back on August 31, 2001. With these two ADEQ documentation, the Company has complied with this one Order.

:msj

Attachment: ADEQ documentation for Mount Tipton and Dolan Springs systems

Cc: Engineering file

Arizona Department of Environmental Quality
Drinking Water Compliance Enforcement Unit
 3033 N. Central Avenue, M0501B
 Phoenix, AZ 85012

Compliance Status Report

PWS Name: Mt. Tipton Water Co.

PWS ID #: 08-059

Compliance Status: No Major Deficiencies Major Deficiencies

Comments:

Date of last inspection / sanitary survey: 1-8-01

Major Operation and Maintenance Deficiencies cited during inspection:

- | | | |
|--|---|---|
| <input checked="" type="checkbox"/> None | <input type="checkbox"/> unable to maintain 20psi | <input type="checkbox"/> inadequate storage |
| | <input type="checkbox"/> cross connection/backflow problems | <input type="checkbox"/> surface water treatment rule |
| | <input type="checkbox"/> treatment deficiencies | <input type="checkbox"/> approval of construction |
| | <input type="checkbox"/> certified operator | |

Administrative Orders:

Is ADEQ administrative order in effect? Yes No

Is US EPA administrative order in effect? Yes No

Comments:

System information:

Number of Points of Entry 4 Population Served 2000 Connections Served 644
 Initial Monitoring Year 1994 MAP year 2000

DWCE Evaluation completed by: Jim Puckert

Phone: 602-207-4649 **Date:** 8-31-01

Based on data submitted by the water system, ADEQ has determined that this system is currently delivering water that meets water quality standards required by Arizona Administrative Code, Title 18, Chapter 4. This compliance status report does not guarantee the water quality for this system in the future. This compliance status report does not reflect the status of any other water system owned by this utility company.

Arizona Department of Environmental Quality
Drinking Water Compliance Enforcement Unit
3033 N. Central Avenue, M0501B
Phoenix, AZ 85012

NO. 260 1002

Compliance Status Report

PWS Name: Dolan Springs Water System

PWS ID #: 08-023

Compliance Status: No Major Deficiencies Major Deficiencies

Comments:

Date of last inspection / sanitary survey: 7-9-99

Major Operation and Maintenance Deficiencies cited during inspection:

- None unable to maintain 20psi inadequate storage
 cross connection/backflow problems surface water treatment rule
 treatment deficiencies approval of construction
 certified operator

Administrative Orders:

Is ADEQ administrative order in effect? Yes No

Is US EPA administrative order in effect? Yes No

Comments:

System Information:

Number of Points of Entry 1 Population Served 320 Connections Served 154

Initial Monitoring Year 1995 MAP year 2001

DWCE Evaluation completed by: Jim Puckert

Phone: 602-207-4649 Date: 2-5-2002

Based on data submitted by the water system, ADEQ has determined that this system is currently delivering water that meets water quality standards required by Arizona Administrative Code, Title 18, Chapter 4. This compliance status report does not guarantee the water quality for this system in the future. This compliance status report does not reflect the status of any other water system owned by this utility company.