



0000040091

Arizona Department of Environmental Conservation
Water Quality Compliance Assurance Unit
1110 W. Washington Street, 5415B-1
Phoenix, AZ 85007

Drinking Water Compliance Status Report

Public Water System Name: Lyn-Lee Water Co.

Public Water System ID #: 10-007

Public Water System Type: CO Non-transient Non-community Transient Non-community

Overall Compliance Status: No Major Deficiencies Major Deficiencies

Monitoring and Reporting Status: No Major Deficiencies Major Deficiencies
Comments:

Operation and Maintenance Status: No Major Deficiencies Major Deficiencies
Comments:

Major unresolved/ongoing operation and maintenance deficiencies:

- unable to maintain 20psi
- cross connection/backflow problems
- treatment deficiencies
- certified operator
- inadequate storage
- surface water treatment rule
- approval of construction
- other

Date of last inspection / sanitary survey: 2-16-05

Administrative Orders:
Is an ADEQ administrative order in effect? Yes No
Comments:

System information:

Number of Points of Entry 1 Number of Sources 2 Population Served 195

Service Connections 65 Initial Monitoring Year 1995 Initial MAP Year 2005

Evaluation completed by: Jim Puckett

Phone: 602-771-4649 Date: 1-19-06

Based upon data submitted by the water system, ADEQ has determined that this system is currently delivering water that meets water quality standards required by Arizona Administrative Code, Title 18, Chapter 4. This compliance status report does not guarantee the water quality for this system in the future. This compliance status report does not reflect the status of any other water system owned by this utility company.

RECEIVED
ARIZONA CORP. COMM. CONTROL
TUCSON, AZ
2006 FEB -1 P 2:19

W-01854 A-05-0543

