

ORIGINAL

OPEN MEETING AGENDA ITEM

JOHNSON UTILITIES, L.L.C



0000041175

5230 East Shea Boulevard * Scottsdale, Arizona 85254
PH: (480) 998-3300; FAX: (480) 483-7908

50

March 30, 2006

Mr. Ernest Johnson
Arizona Corporation Commission
1200 W. Washington Street
Phoenix, Arizona 85007

RE: Johnson Utilities, L.L.C.: Compliance with Decision No. 65840, 64062
RE: Annual Wastewater Compliance with ADEQ regulations.
WS-02987A-99-0583; WS-02987A-00-0618; W-02234A-00-0371; W-02859A-00-0774;
W-01395A-00-0784

Dear Mr. Johnson:

Pursuant to the above mentioned decisions, Johnson Utilities hereby submits this compliance filing in accordance with the Commission's orders. Enclosed please find the Arizona Department of Environmental Quality's (ADEQ) Compliance Status letters for the Pecan, San Tan, and Section 11 Waste Water Treatment Plants attached hereto as Attachments 1, 2, and 3 respectively. All three letters indicate the facilities are in full compliance with ADEQ regulations. Should you have any questions or concerns, please do not hesitate to contact me. Thank you for your time and consideration in this matter.

Sincerely,

Daniel Hodges
Johnson Utilities, LLC

RECEIVED
2006 MAR 30 P 2:22
AZ CORP COMMISSION
DOCUMENT CONTROL

Cc: Brian Bozzo, Compliance Manager
Richard Sallquist, Sallquist, Drummond & O'Connor
Docket Control

ATTACHMENT 1



Janet Napolitano
Governor

ARIZONA DEPARTMENT OF ENVIRONMENTAL QUALITY

1110 West Washington Street • Phoenix, Arizona 85007
(602) 771-2300 • www.adeq.state.az.us



Stephen A. Owens
Director

March 28, 2006

Johnson Utilities Company
Mr. Daniel Hodges
5230 E. Shea Blvd, Suit 200
Scottsdale, AZ 85254

RE: Compliance Status for Pecan Water Reclamation, Inventory number P-105324,
Place Id: 18583, Permit number: 29510.

Dear Mr. Hodges;

Your request for evaluation of compliance status for the above facility is completed. Our records indicate that Pecan Water Reclamation has Aquifer Protection Permit number 29510.

The Aquifer Protection Permit reporting requirements and monitoring results which have been submitted indicate the facility is in compliance based on the current information that is available to ADEQ and no enforcement actions are pending.

It should be understood that the compliance status of a facility may change from time to time based upon monitoring results or a facility inspection. Therefore this is based on the most current information available.

Sincerely,

Fred Vakili, EHS II
Water Quality Data Unit
Water Quality Compliance Section

Northern Regional Office
1515 East Cedar Avenue • Suite F • Flagstaff, AZ 86004
(928) 779-0313

Southern Regional Office
400 West Congress Street • Suite 433 • Tucson, AZ 85701
(520) 628-6733

ATTACHMENT 2



Janet Napolitano
Governor

ARIZONA DEPARTMENT OF ENVIRONMENTAL QUALITY

1110 West Washington Street • Phoenix, Arizona 85007
(602) 771-2300 • www.adeq.state.az.us



Stephen A. Owens
Director

March 28, 2006

Johnson Utilities Company
Mr. Daniel Hodges
5230 E. Shea Blvd, Suit 200
Scottsdale, AZ 85254

RE: Compliance Status for San Tan WWTP, Inventory number P-105325,
Place Id: 18584, Permit number: 29511.

Dear Mr. Hodges;

Your request for evaluation of compliance status for the above facility is completed. Our records indicate that San Tan WWTP has Aquifer Protection Permit number 29510.

The Aquifer Protection Permit reporting requirements and monitoring results which have been submitted indicate the facility is **in compliance** based on the current information that is available to ADEQ and no enforcement actions are pending.

It should be understood that the compliance status of a facility may change from time to time based upon monitoring results or a facility inspection. Therefore this is based on the most current information available.

Sincerely,

Fred Vakili, EHS II
Water Quality Data Unit
Water Quality Compliance Section

Northern Regional Office
1515 East Cedar Avenue • Suite F • Flagstaff, AZ 86004
(928) 779-0313

Southern Regional Office
400 West Congress Street • Suite 433 • Tucson, AZ 85701
(520) 628-6733

ATTACHMENT 3



Janet Napolitano
Governor

ARIZONA DEPARTMENT OF ENVIRONMENTAL QUALITY

1110 West Washington Street • Phoenix, Arizona 85007
(602) 771-2300 • www.adeq.state.az.us



Stephen A. Owens
Director

March 28, 2006

Johnson Utilities Company
Mr. Daniel Hodges
5230 E. Shea Blvd, Suit 200
Scottsdale, AZ 85254

RE: Compliance Status for section 11 WWTP, Inventory number P-103081,
Place Id: 142, Permit number: 24069.

Dear Mr. Hodges;

Your request for evaluation of compliance status for the above facility is completed. Our records indicate that Section 11 WWTP has Aquifer Protection Permit number 29510.

The Aquifer Protection Permit reporting requirements and monitoring results which have been submitted indicate the facility is in compliance based on the current information that is available to ADEQ and no enforcement actions are pending.

It should be understood that the compliance status of a facility may change from time to time based upon monitoring results or a facility inspection. Therefore this is based on the most current information available.

Sincerely,

Fred Vakili, EHS II
Water Quality Data Unit
Water Quality Compliance Section

Northern Regional Office
1515 East Cedar Avenue • Suite F • Flagstaff, AZ 86004
(928) 779-0313

Southern Regional Office
400 West Congress Street • Suite 433 • Tucson, AZ 85701
(520) 628-6733