



0000041188

# JOHNSON UTILITIES, L.L.C

5230 East Shea Boulevard \* Scottsdale, Arizona 85254  
PH: (480) 998-3300; FAX: (480) 483-7908

ORIGINAL

50

April 7, 2006

Mr. Brian Bozzo  
Arizona Corporation Commission  
1200 W. Washington Street  
Phoenix, Arizona 85007

RE: Johnson Utilities, L.L.C.: Compliance with Decision No. 65840, 64062  
RE: Annual Water Compliance with ADEQ regulations.  
WS-02987A-99-0583; WS-02987A-00-0618; W-02234A-00-0371; W-02859A-00-0774;  
W-01395A-00-0784

Dear Mr. Johnson:

Pursuant to the above mentioned decisions, Johnson Utilities hereby submits this compliance filing in accordance with the Commission's orders. Enclosed please find the Arizona Department of Environmental Quality's (ADEQ) Drinking Water Compliance Status Report for Systems 11-116, 11-245, and 11-128 attached hereto as Attachments 1, 2, and 3 respectively. All three letters indicate the water facilities are in full compliance with ADEQ regulations. These compliance status reports along with the wastewater compliance status letters filed on March 30, 2006 satisfies our annual requirement to document Johnson Utilities, L.L.C. is in full compliance with ADEQ regulations. Should you have any questions or concerns, please do not hesitate to contact me. Thank you for your time and consideration in this matter.

Sincerely,

Daniel Hodges  
Johnson Utilities, LLC

AZ CORP COMMISSION  
DOCUMENT CONTROL

2006 APR 10 A 8:53

RECEIVED

Cc: Ernest Johnson, Director  
Richard Sallquist, Sallquist, Drummond & O'Connor  
Docket Control

# **ATTACHMENT 1**

**Arizona Department of Environmental Quality**  
**Water Quality Compliance Assurance Unit**  
1110 W. Washington Street, 5415B-1  
Phoenix, AZ 85007

**Drinking Water Compliance Status Report**

**Public Water System Name:** Johnson Utilities - Sun Valley

**Public Water System ID #:** 11-116

**Public Water System Type:**  CO     Non-transient Non-community     Transient Non-community

**Overall Compliance Status:**  No Major Deficiencies     Major Deficiencies

**Monitoring and Reporting Status:**  No Major Deficiencies     Major Deficiencies

Comments:

**Operation and Maintenance Status:**  No Major Deficiencies     Major Deficiencies

Comments:

Major unresolved/ongoing operation and maintenance deficiencies:

- |   |   |
|---|---|
| <input type="checkbox"/> unable to maintain 20psi           | <input type="checkbox"/> inadequate storage           |
| <input type="checkbox"/> cross connection/backflow problems | <input type="checkbox"/> surface water treatment rule |
| <input type="checkbox"/> treatment deficiencies             | <input type="checkbox"/> approval of construction     |
| <input type="checkbox"/> certified operator                 | <input type="checkbox"/> other                        |

Date of last inspection / sanitary survey: 12-30-03

**Administrative Orders:**

Is an ADEQ administrative order in effect?     Yes     No

Comments:

**System information:**

Number of Points of Entry 1                      Number of Sources 1                      Population Served 182

Service Connections 65                      Initial Monitoring Year 1996                      Initial MAP Year 2002

**Evaluation completed by:**    **Jim Puckett**

**Phone:** 602-771-4649                      **Date:** 3-3-06

Based upon data submitted by the water system, ADEQ has determined that this system is currently delivering water that meets water quality standards required by Arizona Administrative Code, Title 18, Chapter 4. This compliance status report does not guarantee the water quality for this system in the future. This compliance status report does not reflect the status of any other water system owned by this utility company.

# ATTACHMENT 2

**Arizona Department of Environmental Quality**  
**Water Quality Compliance Assurance Unit**  
1110 W. Washington Street, 5415B-1  
Phoenix, AZ 85007

**Drinking Water Compliance Status Report**

**Public Water System Name:** Wildhorse

**Public Water System ID #:** 11-245

**Public Water System Type:**  CO     Non-transient Non-community     Transient Non-community

**Overall Compliance Status:**  No Major Deficiencies     Major Deficiencies

**Monitoring and Reporting Status:**  No Major Deficiencies     Major Deficiencies

Comments:

**Operation and Maintenance Status:**  No Major Deficiencies     Major Deficiencies

Comments:

Major unresolved/ongoing operation and maintenance deficiencies:

- |   |   |
|---|---|
| <input type="checkbox"/> unable to maintain 20psi           | <input type="checkbox"/> inadequate storage           |
| <input type="checkbox"/> cross connection/backflow problems | <input type="checkbox"/> surface water treatment rule |
| <input type="checkbox"/> treatment deficiencies             | <input type="checkbox"/> approval of construction     |
| <input type="checkbox"/> certified operator                 | <input type="checkbox"/> other                        |

Date of last inspection / sanitary survey: none

**Administrative Orders:**

Is an ADEQ administrative order in effect?     Yes     No

Comments:

**System information:**

Number of Points of Entry 1    Number of Sources 1    Population Served 95

Service Connections 34    Initial Monitoring Year 2006    Initial MAP Year 2006

**Evaluation completed by:**    **Jim Puckett**

**Phone: 602-771-4649**    **Date: 3-3-06**

Based upon data submitted by the water system, ADEQ has determine that this system is currently delivering water that meets water quality standards required by Arizona Administrative Code, Title 18, Chapter 4. This compliance status report does not guarantee the water quality for this system in the future. This compliance status report does not reflect the status of any other water system owned by this utility company.

# ATTACHMENT 3



Janet Napolitano  
Governor

# ARIZONA DEPARTMENT OF ENVIRONMENTAL QUALITY

1110 West Washington Street • Phoenix, Arizona 85007  
(602) 771-2300 • www.azdeq.gov



Stephen A. Owens  
Director

March 28, 2006

Mr. Brian Tompsett  
Johnson Utilities, L.L.C.  
5230 East Shea Boulevard  
Scottsdale, AZ 85254

Re: Drinking Water Compliance Status Report: PWS #11-128

Dear Mr. Tompsett:

Thank you for your letter dated March 14, 2006, which raised questions with a recent Drinking Water Compliance Status Report issued for public water system (PWS) #11-128. Enclosed is a new compliance status report dated March 21, 2006, which accurately reflects the information in our database.

We appreciate your bringing this issue to our attention and regret any inconvenience it created for you and your staff. If you have any questions or additional concerns, please contact me directly at (602) 771-4649.

Sincerely,

Jim Puckett, Environmental Health Specialist  
Water Quality Division

Enclosure

cc Patrick Cunningham, Deputy Director  
John Calkins, Drinking Water Section Manager  
Donna Lucchese, Drinking Water Monitoring and Protection Unit

Northern Regional Office  
1515 East Cedar Avenue • Suite F • Flagstaff, AZ 86004  
(520) 779-0313

Southern Regional Office  
400 West Congress Street • Suite 433 • Tucson, AZ 85701  
(520) 628-6733

**Arizona Department of Environmental Quality**  
Water Quality Compliance Assurance Unit  
1110 W. Washington Street, 5415B-1  
Phoenix, AZ 85007

**Drinking Water Compliance Status Report**

Public Water System Name: Johnson Utilities

Public Water System ID #: 11-128

Public Water System Type:             CO     Non-transient Non-community     Transient Non-community

Overall Compliance Status:             No Major Deficiencies             Major Deficiencies

Monitoring and Reporting Status:     No Major Deficiencies             Major Deficiencies

Comments:

Operation and Maintenance Status:    No Major Deficiencies             Major Deficiencies

Comments:

Major unresolved/ongoing operation and maintenance deficiencies:

- |   |   |
|---|---|
| <input type="checkbox"/> unable to maintain 20psi           | <input type="checkbox"/> inadequate storage           |
| <input type="checkbox"/> cross connection/backflow problems | <input type="checkbox"/> surface water treatment rule |
| <input type="checkbox"/> treatment deficiencies             | <input type="checkbox"/> approval of construction     |
| <input type="checkbox"/> certified operator                 | <input type="checkbox"/> other                        |

Date of last inspection / sanitary survey: 1-15-05

**Administrative Orders:**

Is an ADEQ administrative order in effect?     Yes             No

Comments:

**System information:**

Number of Points of Entry 5            Number of Sources 8            Population Served 31124

Service Connections 11613            Initial Monitoring Year 2000            Initial MAP Year 2000

**Evaluation completed by: Jim Puckett**

**Phone: 602-771-4649**

**Date: 3-21-06**

Based upon data submitted by the water system, ADEQ has determined that this system is currently delivering water that meets water quality standards required by Arizona Administrative Code, Title 18, Chapter 4. This compliance status report does not guarantee the water quality for this system in the future. This compliance status report does not reflect the status of any other water system owned by this utility company.