



0000049785

JOHNSON UTILITIES, L.L.C

5230 East Shea Boulevard * Scottsdale, Arizona 85254
PH: (480) 998-3300; FAX: (480) 483-7908

ORIGINAL

50

April 7, 2006

Mr. Brian Bozzo
Arizona Corporation Commission
1200 W. Washington Street
Phoenix, Arizona 85007

RE: Johnson Utilities, L.L.C.: Compliance with Decision No. 65840, 64062
RE: Annual Water Compliance with ADEQ regulations:
WS-02987A-99-0583; WS-02987A-00-0618; W-02234A-00-0371; W-02859A-00-0774;
W-01395A-00-0784

Dear Mr. Johnson:

Pursuant to the above mentioned decisions, Johnson Utilities hereby submits this compliance filing in accordance with the Commission's orders. Enclosed please find the Arizona Department of Environmental Quality's (ADEQ) Drinking Water Compliance Status Report for Systems 11-116, 11-245, and 11-128 attached hereto as Attachments 1, 2, and 3 respectively. All three letters indicate the water facilities are in full compliance with ADEQ regulations. These compliance status reports along with the wastewater compliance status letters filed on March 30, 2006 satisfies our annual requirement to document Johnson Utilities, L.L.C. is in full compliance with ADEQ regulations. Should you have any questions or concerns, please do not hesitate to contact me. Thank you for your time and consideration in this matter.

Sincerely,

Daniel Hodges
Johnson Utilities, LLC

AZ CORP COMMISSION
DOCUMENT CONTROL

2006 APR 10 A 8:53

RECEIVED

Cc: Ernest Johnson, Director
Richard Sallquist, Sallquist, Drummond & O'Connor
Docket Control

ATTACHMENT 1

Arizona Department of Environmental Quality
Water Quality Compliance Assurance Unit
1110 W. Washington Street, 5415B-1
Phoenix, AZ 85007

Drinking Water Compliance Status Report

Public Water System Name: Johnson Utilities - Sun Valley

Public Water System ID #: 11-116

Public Water System Type: CO Non-transient Non-community Transient Non-community

Overall Compliance Status: No Major Deficiencies Major Deficiencies

Monitoring and Reporting Status: No Major Deficiencies Major Deficiencies
Comments:

Operation and Maintenance Status: No Major Deficiencies Major Deficiencies
Comments:

Major unresolved/ongoing operation and maintenance deficiencies:

- | | |
|---|---|
| <input type="checkbox"/> unable to maintain 20psi | <input type="checkbox"/> inadequate storage |
| <input type="checkbox"/> cross connection/backflow problems | <input type="checkbox"/> surface water treatment rule |
| <input type="checkbox"/> treatment deficiencies | <input type="checkbox"/> approval of construction |
| <input type="checkbox"/> certified operator | <input type="checkbox"/> other |

Date of last inspection / sanitary survey: 12-30-03

Administrative Orders:

Is an ADEQ administrative order in effect? Yes No

Comments:

System information:

Number of Points of Entry 1 Number of Sources 1 Population Served 182

Service Connections 65 Initial Monitoring Year 1996 Initial MAP Year 2002

Evaluation completed by: **Jim Puckett**

Phone: 602-771-4649 **Date:** 3-3-06

Based upon data submitted by the water system, ADEQ has determined that this system is currently delivering water that meets water quality standards required by Arizona Administrative Code, Title 18, Chapter 4. This compliance status report does not guarantee the water quality for this system in the future. This compliance status report does not reflect the status of any other water system owned by this utility company.

ATTACHMENT 2

Arizona Department of Environmental Quality
Water Quality Compliance Assurance Unit
1110 W. Washington Street, 5415B-1
Phoenix, AZ 85007

Drinking Water Compliance Status Report

Public Water System Name: Wildhorse

Public Water System ID #: 11-245

Public Water System Type: CO Non-transient Non-community Transient Non-community

Overall Compliance Status: No Major Deficiencies Major Deficiencies

Monitoring and Reporting Status: No Major Deficiencies Major Deficiencies

Comments:

Operation and Maintenance Status: No Major Deficiencies Major Deficiencies

Comments:

Major unresolved/ongoing operation and maintenance deficiencies:

- | | |
|---|---|
| <input type="checkbox"/> unable to maintain 20psi | <input type="checkbox"/> inadequate storage |
| <input type="checkbox"/> cross connection/backflow problems | <input type="checkbox"/> surface water treatment rule |
| <input type="checkbox"/> treatment deficiencies | <input type="checkbox"/> approval of construction |
| <input type="checkbox"/> certified operator | <input type="checkbox"/> other |

Date of last inspection / sanitary survey: none

Administrative Orders:

Is an ADEQ administrative order in effect? Yes No

Comments:

System information:

Number of Points of Entry 1 Number of Sources 1 Population Served 95

Service Connections 34 Initial Monitoring Year 2006 Initial MAP Year 2006

Evaluation completed by: Jim Puckett

Phone: 602-771-4649 **Date:** 3-3-06

Based upon data submitted by the water system, ADEQ has determine that this system is currently delivering water that meets water quality standards required by Arizona Administrative Code, Title 18, Chapter 4. This compliance status report does not guarantee the water quality for this system in the future. This compliance status report does not reflect the status of any other water system owned by this utility company.

ATTACHMENT 3



Janet Napolitano
Governor

ARIZONA DEPARTMENT OF ENVIRONMENTAL QUALITY

1110 West Washington Street • Phoenix, Arizona 85007
(602) 771-2300 • www.azdeq.gov



Stephen A. Owens
Director

March 28, 2006

Mr. Brian Tompsett
Johnson Utilities, L.L.C.
5230 East Shea Boulevard
Scottsdale, AZ 85254

Re: Drinking Water Compliance Status Report: PWS #11-128

Dear Mr. Tompsett:

Thank you for your letter dated March 14, 2006, which raised questions with a recent Drinking Water Compliance Status Report issued for public water system (PWS) #11-128. Enclosed is a new compliance status report dated March 21, 2006, which accurately reflects the information in our database.

We appreciate your bringing this issue to our attention and regret any inconvenience it created for you and your staff. If you have any questions or additional concerns, please contact me directly at (602) 771-4649.

Sincerely,

Jim Puckett, Environmental Health Specialist
Water Quality Division

Enclosure

cc Patrick Cunningham, Deputy Director
John Calkins, Drinking Water Section Manager
Donna Lucchese, Drinking Water Monitoring and Protection Unit

Northern Regional Office
1515 East Cedar Avenue • Suite F • Flagstaff, AZ 86004
(520) 779-0313

Southern Regional Office
400 West Congress Street • Suite 433 • Tucson, AZ 85701
(520) 628-6733

Arizona Department of Environmental Quality
Water Quality Compliance Assurance Unit
1110 W. Washington Street, 5415B-1
Phoenix, AZ 85007

Drinking Water Compliance Status Report

Public Water System Name: Johnson Utilities

Public Water System ID #: 11-128

Public Water System Type: CO Non-transient Non-community Transient Non-community

Overall Compliance Status: No Major Deficiencies Major Deficiencies

Monitoring and Reporting Status: No Major Deficiencies Major Deficiencies

Comments:

Operation and Maintenance Status: No Major Deficiencies Major Deficiencies

Comments:

Major unresolved/ongoing operation and maintenance deficiencies:

- | | |
|---|---|
| <input type="checkbox"/> unable to maintain 20psi | <input type="checkbox"/> inadequate storage |
| <input type="checkbox"/> cross connection/backflow problems | <input type="checkbox"/> surface water treatment rule |
| <input type="checkbox"/> treatment deficiencies | <input type="checkbox"/> approval of construction |
| <input type="checkbox"/> certified operator | <input type="checkbox"/> other |

Date of last inspection / sanitary survey: 1-15-05

Administrative Orders:

Is an ADEQ administrative order in effect? Yes No

Comments:

System information:

Number of Points of Entry 5 Number of Sources 8 Population Served 31124

Service Connections 11613 Initial Monitoring Year 2000 Initial MAP Year 2000

Evaluation completed by: Jim Puckett

Phone: 602-771-4649

Date: 3-21-06

Based upon data submitted by the water system, ADEQ has determined that this system is currently delivering water that meets water quality standards required by Arizona Administrative Code, Title 18, Chapter 4. This compliance status report does not guarantee the water quality for this system in the future. This compliance status report does not reflect the status of any other water system owned by this utility company.