

ORIGINAL



0000059074

For Docket #s W-20395A-05-0536 & W-20378A-05-0536

RECEIVED

ARIZONA DEPARTMENT OF ENVIRONMENTAL QUALITY  
DRINKING WATER MICROBIOLOGICAL ANALYSIS REPORT  
SAMPLES TO BE TAKEN IN DISTRIBUTION SYSTEM ONLY  
PUBLIC WATER SYSTEM INFORMATION

57

2006 SEP 12 A 10:28

AZ CORP COMMISSION  
DOCUMENT CONTROL 032  
SYSTEM ID

Arizona Corporation Commission  
DOCKETED

DATELAND WATER CO.  
SYSTEM NAME

7-2-06 / 17:48  
SAMPLE DATE / TIME

SEP 12 2006

RICK MILLER  
OWNER / CONTACT PERSON

(928) 341-9196  
CONTACT FAX NUMBER

DOCKETED BY *pm*

(928) 341-9685  
CONTACT PHONE NUMBER

SAMPLE TYPE  
 COMPLIANCE MONITORING

USE IF INITIAL SAMPLE WAS POSITIVE

- ORIGINAL VIOLATING SPECIMEN NUMBER
- REPEAT, ORIGINAL LOCATION
  - REPEAT, OTHER LOCATION
  - REPEAT, DOWNSTREAM LOCATION
  - REPEAT, UPSTREAM LOCATION
  - 400 mL REPEAT (SINGLE TAP ONLY)
  - 300 mL REPEAT (SINGLE TAP ONLY)

SAMPLE SITE ID  
TRAILER SAMPLE TAP

MICROBIOLOGICAL ANALYSIS						
TO BE FILLED OUT BY LABORATORY PERSONNEL						
ANALYSIS METHOD	MCL VALUE	CONTAMINANT NAME	CONT. CODE	TEST START DATE / TIME	ANALYSIS RUN DATE / TIME	RESULT
9223B	PRESENT /1	TOTAL COLIFORM	3000	7-3-06 / 08:06	7-4-06 / 08:40	(+)
ONLY REPORT FECAL RESULT IF TOTAL COLIFORM RESULT IS POSITIVE						
ANALYSIS METHOD	MCL VALUE	CONTAMINANT NAME	CONT. CODE	TEST START DATE / TIME	ANALYSIS RUN DATE / TIME	RESULT
9223B	PRESENT/1	E.coli	3013	7-3-06 / 08:06	7-4-06 / 08:40	(+)

LABORATORY INFORMATION

SPECIMEN NUMBER

70603-DWC-02

ID NUMBER: AZ 0678 FAR WEST WATER& SEWER, INC. LABORATORY 14000 E. COUNTY 14th ST YUMA 928-342 6042

COMMENTS

AUTHORIZED SIGNATURE

*[Signature]*

DATE PUBLIC WATER SYSTEM NOTIFIED

PER PHONE CALL 7-4-06

DWAR1 REV 11/05/99

PAGE 1 OF 1

FIXED

ARIZONA DEPARTMENT OF ENVIRONMENTAL QUALITY  
**DRINKING WATER MICROBIOLOGICAL ANALYSIS REPORT**  
 SAMPLES TO BE TAKEN IN DISTRIBUTION SYSTEM ONLY  
 PUBLIC WATER SYSTEM INFORMATION

14-032  
 SYSTEM ID

DATELAND WATER CO.  
 SYSTEM NAME

7-6-06 / 08:00  
 SAMPLE DATE/ TIME

RICK MILLER  
 OWNER / CONTACT PERSON

(928) 341-9196  
 CONTACT FAX NUMBER

(928) 341-9685  
 CONTACT PHONE NUMBER

SAMPLE TYPE  
X COMPLIANCE MONITORING

USE IF INITIAL SAMPLE WAS POSITIVE

- ORIGINAL VIOLATING SPECIMEN NUMBER
- |                          |                                 |
|--------------------------|---------------------------------|
| <input type="checkbox"/> | REPEAT, ORIGINAL LOCATION       |
| <input type="checkbox"/> | REPEAT, OTHER LOCATION          |
| <input type="checkbox"/> | REPEAT, DOWNSTREAM LOCATION     |
| <input type="checkbox"/> | REPEAT, UPSTREAM LOCATION       |
| <input type="checkbox"/> | 400 mL REPEAT (SINGLE TAP ONLY) |
| <input type="checkbox"/> | 300 mL REPEAT (SINGLE TAP ONLY) |

SAMPLE SITE ID  
SALES TRAILER

MICROBIOLOGICAL ANALYSIS						
TO BE FILLED OUT BY LABORATORY PERSONNEL						
ANALYSIS	MCL	CONTAMINANT	CONT.	TEST START	ANALYSIS RUN	RESULT
METHOD	VALUE	NAME	CODE	DATE / TIME	DATE / TIME	
9223B	PRESENT /1	TOTAL COLIFORM	3000	7-6-06 / 11:08	7-7-06 / 12:25	(-)
ONLY REPORT FECAL RESULT IF TOTAL COLIFORM RESULT IS POSITIVE						
ANALYSIS	MCL	CONTAMINANT	CONT.	TEST START	ANALYSIS RUN	RESULT
METHOD	VALUE	NAME	CODE	DATE / TIME	DATE / TIME	
9223B	PRESENT/1	E.coli	3013			


LABORATORY INFORMATION

SPECIMEN NUMBER  
60706-DW3-15

ID NUMBER: AZ 0678 FAR WEST WATER & SEWER, INC. LABORATORY 14000 E. COUNTY 14th ST YUMA 928-342 6042

COMMENTS \_\_\_\_\_

AUTHORIZED SIGNATURE \_\_\_\_\_



DATE PUBLIC WATER SYSTEM NOTIFIED \_\_\_\_\_

ARIZONA DEPARTMENT OF ENVIRONMENTAL QUALITY  
**DRINKING WATER MICROBIOLOGICAL ANALYSIS REPORT**  
 SAMPLES TO BE TAKEN IN DISTRIBUTION SYSTEM ONLY  
 PUBLIC WATER SYSTEM INFORMATION

14-032  
 SYSTEM ID

DATELAND WATER CO.  
 SYSTEM NAME

7-6-06 / 08:10  
 SAMPLE DATE / TIME

RICK MILLER  
 OWNER / CONTACT PERSON

(928) 341-9196  
 CONTACT FAX NUMBER

(928) 341-9685  
 CONTACT PHONE NUMBER

SAMPLE TYPE  
X COMPLIANCE MONITORING

USE IF INITIAL SAMPLE WAS POSITIVE

ORIGINAL VIOLATING SPECIMEN NUMBER

- |                          |                                 |
|--------------------------|---------------------------------|
| <input type="checkbox"/> | REPEAT, ORIGINAL LOCATION       |
| <input type="checkbox"/> | REPEAT, OTHER LOCATION          |
| <input type="checkbox"/> | REPEAT, DOWNSTREAM LOCATION     |
| <input type="checkbox"/> | REPEAT, UPSTREAM LOCATION       |
| <input type="checkbox"/> | 400 mL REPEAT (SINGLE TAP ONLY) |
| <input type="checkbox"/> | 300 mL REPEAT (SINGLE TAP ONLY) |

SAMPLE SITE ID  
SE RV LOT

**MICROBIOLOGICAL ANALYSIS**

TO BE FILLED OUT BY LABORATORY PERSONNEL

ANALYSIS METHOD	MCL VALUE	CONTAMINANT NAME	CONT. CODE	TEST START DATE / TIME	ANALYSIS RUN DATE / TIME	RESULT
9223B	PRESENT /1	TOTAL COLIFORM	3000	7-6-06 / 11:09	7-7-06 / 12:25	(-)

ONLY REPORT FECAL RESULT IF TOTAL COLIFORM RESULT IS POSITIVE

ANALYSIS METHOD	MCL VALUE	CONTAMINANT NAME	CONT. CODE	TEST START DATE / TIME	ANALYSIS RUN DATE / TIME	RESULT
9223B	PRESENT/1	<i>E. coli</i>	3013			

**LABORATORY INFORMATION**

SPECIMEN NUMBER

60706-DW4-16

ID NUMBER: AZ 0678 FAR WEST WATER & SEWER, INC. LABORATORY 14000 E. COUNTY 14th ST YUMA 928-342 6042

COMMENTS \_\_\_\_\_

AUTHORIZED SIGNATURE \_\_\_\_\_



DATE PUBLIC WATER SYSTEM NOTIFIED \_\_\_\_\_

ARIZONA DEPARTMENT OF ENVIRONMENTAL QUALITY  
**DRINKING WATER MICROBIOLOGICAL ANALYSIS REPORT**  
 SAMPLES TO BE TAKEN IN DISTRIBUTION SYSTEM ONLY  
 PUBLIC WATER SYSTEM INFORMATION

14-032  
 SYSTEM ID

DATELAND WATER CO.  
 SYSTEM NAME

7-6-06 / 07:45  
 SAMPLE DATE/ TIME

RICK MILLER  
 OWNER / CONTACT PERSON

(928) 341-9196  
 CONTACT FAX NUMBER

(928) 341-9685  
 CONTACT PHONE NUMBER

SAMPLE TYPE  
X COMPLIANCE MONITORING

USE IF INITIAL SAMPLE WAS POSITIVE

- ORIGINAL VIOLATING SPECIMEN NUMBER
- |                          |                                 |
|--------------------------|---------------------------------|
| <input type="checkbox"/> | REPEAT, ORIGINAL LOCATION       |
| <input type="checkbox"/> | REPEAT, OTHER LOCATION          |
| <input type="checkbox"/> | REPEAT, DOWNSTREAM LOCATION     |
| <input type="checkbox"/> | REPEAT, UPSTREAM LOCATION       |
| <input type="checkbox"/> | 400 mL REPEAT (SINGLE TAP ONLY) |
| <input type="checkbox"/> | 300 mL REPEAT (SINGLE TAP ONLY) |

SAMPLE SITE ID  
BAR

MICROBIOLOGICAL ANALYSIS						
TO BE FILLED OUT BY LABORATORY PERSONNEL						
ANALYSIS	MCL	CONTAMINANT	CONT.	TEST START	ANALYSIS RUN	RESULT
METHOD	VALUE	NAME	CODE	DATE / TIME	DATE / TIME	
9223B	PRESENT /1	TOTAL COLIFORM	3000	7-6-06 / 11:07	7-7-06 / 12:25	(-)
ONLY REPORT FECAL RESULT IF TOTAL COLIFORM RESULT IS POSITIVE						
ANALYSIS	MCL	CONTAMINANT	CONT.	TEST START	ANALYSIS RUN	RESULT
METHOD	VALUE	NAME	CODE	DATE / TIME	DATE / TIME	
9223B	PRESENT/1	E.coli	3013			

**LABORATORY INFORMATION**

SPECIMEN NUMBER  
60706-DW2-14

ID NUMBER: AZ 0678 FAR WEST WATER& SEWER, INC. LABORATORY, 14000 E. COUNTY 14th ST YUMA 928-342 6042

COMMENTS \_\_\_\_\_  
 AUTHORIZED SIGNATURE   
 DATE PUBLIC WATER SYSTEM NOTIFIED \_\_\_\_\_



ARIZONA DEPARTMENT OF ENVIRONMENTAL QUALITY  
**DRINKING WATER MICROBIOLOGICAL ANALYSIS REPORT**  
 SAMPLES TO BE TAKEN IN DISTRIBUTION SYSTEM ONLY  
 PUBLIC WATER SYSTEM INFORMATION

14-032  
 SYSTEM ID

DATELAND WATER CO.  
 SYSTEM NAME

8-9-06 / 07:25  
 SAMPLE DATE/ TIME

RICK MILLER  
 OWNER / CONTACT PERSON

(928) 341-9196  
 CONTACT FAX NUMBER

(928) 341-9685  
 CONTACT PHONE NUMBER

SAMPLE TYPE  
X COMPLIANCE MONITORING

USE IF INITIAL SAMPLE WAS POSITIVE

ORIGINAL VIOLATING SPECIMEN NUMBER	
<input type="checkbox"/>	REPEAT, ORIGINAL LOCATION
<input type="checkbox"/>	REPEAT, OTHER LOCATION
<input type="checkbox"/>	REPEAT, DOWNSTREAM LOCATION
<input type="checkbox"/>	REPEAT, UPSTREAM LOCATION
<input type="checkbox"/>	400 mL REPEAT (SINGLE TAP ONLY)
<input type="checkbox"/>	300 mL REPEAT (SINGLE TAP ONLY)

SAMPLE SITE ID  
CHARLIE'S HARLEY

MICROBIOLOGICAL ANALYSIS						
TO BE FILLED OUT BY LABORATORY PERSONNEL						
ANALYSIS METHOD	MCL VALUE	CONTAMINANT NAME	CONT. CODE	TEST START DATE / TIME	ANALYSIS RUN DATE / TIME	RESULT
9223B	PRESENT /1	TOTAL COLIFORM	3000	8-9-06 / 09:56	8-10-06 / 11:00	(-)
ONLY REPORT FECAL RESULT IF TOTAL COLIFORM RESULT IS POSITIVE						
ANALYSIS METHOD	MCL VALUE	CONTAMINANT NAME	CONT. CODE	TEST START DATE / TIME	ANALYSIS RUN DATE / TIME	RESULT
9223B	PRESENT/1	<i>E.coli</i>	3013			

**LABORATORY INFORMATION**

SPECIMEN NUMBER

60809-DW-12

ID NUMBER: AZ 0678 FAR WEST WATER& SEWER, INC. LABORATORY 14000 E. COUNTY 14th ST YUMA 928-342 6042

COMMENTS \_\_\_\_\_

AUTHORIZED SIGNATURE \_\_\_\_\_

DATE PUBLIC WATER SYSTEM NOTIFIED \_\_\_\_\_

**ARIZONA DEPARTMENT OF ENVIRONMENTAL QUALITY  
DRINKING WATER MICROBIOLOGICAL ANALYSIS REPORT  
SAMPLES TO BE TAKEN IN DISTRIBUTION SYSTEM ONLY  
PUBLIC WATER SYSTEM INFORMATION**

14-032  
SYSTEM ID

DATELAND WATER CO.  
SYSTEM NAME

8-9-06 / 07:40  
SAMPLE DATE / TIME

RICK MILLER  
OWNER / CONTACT PERSON

(928) 341-9196  
CONTACT FAX NUMBER

(928) 341-9685  
CONTACT PHONE NUMBER

SAMPLE TYPE  
 COMPLIANCE MONITORING

USE IF INITIAL SAMPLE WAS POSITIVE

ORIGINAL VIOLATING SPECIMEN NUMBER	
<input type="checkbox"/>	REPEAT, ORIGINAL LOCATION
<input type="checkbox"/>	REPEAT, OTHER LOCATION
<input type="checkbox"/>	REPEAT, DOWNSTREAM LOCATION
<input type="checkbox"/>	REPEAT, UPSTREAM LOCATION
<input type="checkbox"/>	400 mL REPEAT (SINGLE TAP ONLY)
<input type="checkbox"/>	300 mL REPEAT (SINGLE TAP ONLY)

SAMPLE SITE ID  
EAST SIDE TRAILER

MICROBIOLOGICAL ANALYSIS						
TO BE FILLED OUT BY LABORATORY PERSONNEL						
ANALYSIS METHOD	MCL VALUE	CONTAMINANT NAME	CONT. CODE	TEST START DATE / TIME	ANALYSIS RUN DATE / TIME	RESULT
9223B	PRESENT /1	TOTAL COLIFORM	3000	8-9-06 / 09:57	8-10-06 / 11:00	(-)
ONLY REPORT FECAL RESULT IF TOTAL COLIFORM RESULT IS POSITIVE						
ANALYSIS METHOD	MCL VALUE	CONTAMINANT NAME	CONT. CODE	TEST START DATE / TIME	ANALYSIS RUN DATE / TIME	RESULT
9223B	PRESENT/1	<i>E.coli</i>	3013			

**LABORATORY INFORMATION**

SPECIMEN NUMBER

60809-DW-13

ID NUMBER: AZ 0678 FAR WEST WATER& SEWER, INC. LABORATORY 14000 E. COUNTY 14th ST YUMA 928-342 6042

COMMENTS \_\_\_\_\_

AUTHORIZED SIGNATURE \_\_\_\_\_

DATE PUBLIC WATER SYSTEM NOTIFIED \_\_\_\_\_

ARIZONA DEPARTMENT OF ENVIRONMENTAL QUALITY  
**DRINKING WATER MICROBIOLOGICAL ANALYSIS REPORT**  
 SAMPLES TO BE TAKEN IN DISTRIBUTION SYSTEM ONLY  
 PUBLIC WATER SYSTEM INFORMATION

14-032  
 SYSTEM ID

DATLAND WATER CO.  
 SYSTEM NAME

8-9-06 / 07:50  
 SAMPLE DATE / TIME

RICK MILLER  
 OWNER / CONTACT PERSON

(928) 341-9196  
 CONTACT FAX NUMBER

(928) 341-9685  
 CONTACT PHONE NUMBER

SAMPLE TYPE  
 COMPLIANCE MONITORING

USE IF INITIAL SAMPLE WAS POSITIVE

- ORIGINAL VIOLATING SPECIMEN NUMBER
- REPEAT, ORIGINAL LOCATION
  - REPEAT, OTHER LOCATION
  - REPEAT, DOWNSTREAM LOCATION
  - REPEAT, UPSTREAM LOCATION
  - 400 mL REPEAT (SINGLE TAP ONLY)
  - 300 mL REPEAT (SINGLE TAP ONLY)

SAMPLE SITE ID  
BAR


MICROBIOLOGICAL ANALYSIS						
TO BE FILLED OUT BY LABORATORY PERSONNEL						
ANALYSIS METHOD	MCL VALUE	CONTAMINANT NAME	CONT. CODE	TEST START DATE / TIME	ANALYSIS RUN DATE / TIME	RESULT
9223B	PRESENT /1	TOTAL COLIFORM	3000	8-9-06 / 09:58	8-10-06 / 11:00	(-)
ONLY REPORT FECAL RESULT IF TOTAL COLIFORM RESULT IS POSITIVE						
ANALYSIS METHOD	MCL VALUE	CONTAMINANT NAME	CONT. CODE	TEST START DATE / TIME	ANALYSIS RUN DATE / TIME	RESULT
9223B	PRESENT/1	E.coli	3013			

**LABORATORY INFORMATION**

SPECIMEN NUMBER  
60809-DW-14

ID NUMBER: AZ 0678 FAR WEST WATER& SEWER, INC. LABORATORY 14000 E. COUNTY 14th ST YUMA 928-342 6042

COMMENTS \_\_\_\_\_

AUTHORIZED SIGNATURE 

DATE PUBLIC WATER SYSTEM NOTIFIED \_\_\_\_\_

ARIZONA DEPARTMENT OF ENVIRONMENTAL QUALITY  
**DRINKING WATER MICROBIOLOGICAL ANALYSIS REPORT**  
 SAMPLES TO BE TAKEN IN DISTRIBUTION SYSTEM ONLY  
 PUBLIC WATER SYSTEM INFORMATION

14-032  
 SYSTEM ID

DATELAND WATER CO.  
 SYSTEM NAME

8-9-06 / 07:35  
 SAMPLE DATE / TIME

RICK MILLER  
 OWNER / CONTACT PERSON

(928) 341-9196  
 CONTACT FAX NUMBER

(928) 341-9685  
 CONTACT PHONE NUMBER

SAMPLE TYPE  
 COMPLIANCE MONITORING

USE IF INITIAL SAMPLE WAS POSITIVE

ORIGINAL VIOLATING SPECIMEN NUMBER

- REPEAT, ORIGINAL LOCATION
- REPEAT, OTHER LOCATION
- REPEAT, DOWNSTREAM LOCATION
- REPEAT, UPSTREAM LOCATION
- 400 mL REPEAT (SINGLE TAP ONLY)
- 300 mL REPEAT (SINGLE TAP ONLY)

SAMPLE SITE ID  
 TANK

MICROBIOLOGICAL ANALYSIS						
TO BE FILLED OUT BY LABORATORY PERSONNEL						
ANALYSIS METHOD	MCL VALUE	CONTAMINANT NAME	CONT. CODE	TEST START DATE / TIME	ANALYSIS RUN DATE / TIME	RESULT
9223B	PRESENT /1	TOTAL COLIFORM	3000	8-9-06 / 09:59	8-10-06 / 11:00	(-)
ONLY REPORT FECAL RESULT IF TOTAL COLIFORM RESULT IS POSITIVE						
ANALYSIS METHOD	MCL VALUE	CONTAMINANT NAME	CONT. CODE	TEST START DATE / TIME	ANALYSIS RUN DATE / TIME	RESULT
9223B	PRESENT/1	<i>E.coli</i>	3013			

LABORATORY INFORMATION

SPECIMEN NUMBER

60809-DW-15

ID NUMBER: AZ 0678 FAR WEST WATER & SEWER, INC. LABORATORY 14000 E. COUNTY 14th ST YUMA 928-342 6042

COMMENTS

AUTHORIZED SIGNATURE

DATE PUBLIC WATER SYSTEM NOTIFIED

ARIZONA DEPARTMENT OF ENVIRONMENTAL QUALITY  
**DRINKING WATER MICROBIOLOGICAL ANALYSIS REPORT**  
 SAMPLES TO BE TAKEN IN DISTRIBUTION SYSTEM ONLY  
 PUBLIC WATER SYSTEM INFORMATION

14-032  
 SYSTEM ID

DATELAND WATER CO.  
 SYSTEM NAME

8-9-06 / 07:20  
 SAMPLE DATE / TIME

RICK MILLER  
 OWNER / CONTACT PERSON

(928) 341-9196  
 CONTACT FAX NUMBER

(928) 341-9685  
 CONTACT PHONE NUMBER

SAMPLE TYPE  
 COMPLIANCE MONITORING

USE IF INITIAL SAMPLE WAS POSITIVE

- ORIGINAL VIOLATING SPECIMEN NUMBER
- |                          |                                 |
|--------------------------|---------------------------------|
| <input type="checkbox"/> | REPEAT, ORIGINAL LOCATION       |
| <input type="checkbox"/> | REPEAT, OTHER LOCATION          |
| <input type="checkbox"/> | REPEAT, DOWNSTREAM LOCATION     |
| <input type="checkbox"/> | REPEAT, UPSTREAM LOCATION       |
| <input type="checkbox"/> | 400 mL REPEAT (SINGLE TAP ONLY) |
| <input type="checkbox"/> | 300 mL REPEAT (SINGLE TAP ONLY) |

SAMPLE SITE ID  
VER'S TIRE SHOP

MICROBIOLOGICAL ANALYSIS						
TO BE FILLED OUT BY LABORATORY PERSONNEL						
ANALYSIS METHOD	MCL VALUE	CONTAMINANT NAME	CONT. CODE	TEST START DATE / TIME	ANALYSIS RUN DATE / TIME	RESULT
9223B	PRESENT /1	TOTAL COLIFORM	3000	8-9-06 / 09:55	8-10-06 / 11:00	(-)
ONLY REPORT FECAL RESULT IF TOTAL COLIFORM RESULT IS POSITIVE						
ANALYSIS METHOD	MCL VALUE	CONTAMINANT NAME	CONT. CODE	TEST START DATE / TIME	ANALYSIS RUN DATE / TIME	RESULT
9223B	PRESENT/1	<i>E.coli</i>	3013			

LABORATORY INFORMATION

SPECIMEN NUMBER

60809-DW-11

ID NUMBER: AZ 0678 FAR WEST WATER & SEWER, INC. LABORATORY 14000 E. COUNTY 14th ST YUMA 928-342 6042

COMMENTS \_\_\_\_\_

AUTHORIZED SIGNATURE \_\_\_\_\_

DATE PUBLIC WATER SYSTEM NOTIFIED \_\_\_\_\_