



0000068597

ORIGINAL

BEFORE THE ARIZONA CORPORATION COMMISSION

RECEIVED

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28

COMMISSIONERS
MARC SPITZER - Chairman
WILLIAM A. MUNDELL
JEFF HATCH-MILLER
MIKE GLEASON
KRISTIN K. MAYES

2003 DEC 22 A 9:58

AZ CORP COMMISSION
DOCUMENT CONTROL

IN THE MATTER OF THE APPLICATION OF
MOUNT TIPTON WATER COMPANY, INC.
FOR AN EMERGENCY RATE INCREASE.

DOCKET NO. W-02105A-03-0805

AMENDED
STAFF'S NOTICE OF FILING
LATE-FILED EXHIBIT

Staff of the Utilities Division of the Arizona Corporation Commission hereby amends its previously filed "Late-Filed Exhibit". Since the original Response filing, in the above-referenced matter, the Mount Tipton Water Company ("Applicant") has provided Staff with documentation of the most recent "Drinking Water Compliance Status Report" issued by the Arizona Department of Environmental Quality ("ADEQ"). Staff agrees that the attached report from ADEQ dated December 19, 2003 demonstrates that the Applicant is currently in compliance.

RESPECTFULLY SUBMITTED this 22nd day of December 2003.

Arizona Corporation Commission

DOCKETED

DEC 22 2003

DOCKETED BY *CM*

Lisa A. Vandenberg
Attorney, Legal Division
Arizona Corporation Commission
1200 West Washington Street
Phoenix, Arizona 85007
(602) 542-3402

The original and thirteen (13) copies of the foregoing were filed this 22nd day of December, 2003 with:

Docket Control
Arizona Corporation Commission
1200 West Washington Street
Phoenix, Arizona 85007

1 Copies of the foregoing were
2 mailed this 22nd day of December,
3 2003 to:

4 Sue Morgan
5 Assistant General Manager
6 Mount Tipton Water Company, Inc.
7 P.O. Box 38
8 Dolan Springs, Arizona 86441-0038

9 Nancy Roe
10 Secretary to Lisa A. Vandenberg
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28

Arizona Department of Environmental Quality
Water Quality Compliance Assurance Unit
1110 W. Washington Street, 5415B-1
Phoenix, AZ 85007

Drinking Water Compliance Status Report

Public Water System Name: Mt. Tipton Water Co.

Public Water System ID #: 08-059

Overall Compliance Status: No Major Deficiencies Major Deficiencies

Monitoring and Reporting Status: No Major Deficiencies Major Deficiencies

Comments:

Operation and Maintenance Status: No Major Deficiencies Major Deficiencies

Comments:

Major unresolved/ongoing operation and maintenance deficiencies:

- unable to maintain 20psi
- cross connection/backflow problems
- treatment deficiencies
- certified operator
- inadequate storage
- surface water treatment rule
- approval of construction
- other

Date of last inspection / sanitary survey: 01/14/01

Administrative Orders:

Is an ADEQ administrative order in effect? Yes No

Comments:

System Information:

Number of Points of Entry 9 Number of Sources 9 Population Served 2000

Service Connections 800 Initial Monitoring Year 1994 Initial MAP Year 2000

Evaluation completed by: John Calkins, Supervisor Water Quality Compliance Assurance Unit

Phone: (602) 771-4651 Date: 12/19/03

Based on data submitted by the water system, ADEQ has determined that this system is currently delivering water that meets water quality standards required by Arizona Administrative Code, Title 18, Chapter 4. This compliance status report does not guarantee the water quality for this system in the future. This compliance status report does not reflect the status of any other water system owned by this utility company.