

ORIGINAL



0000076116

SALLQUIST, DRUMMOND & O'CONNOR, P.C.
ATTORNEYS AT LAW
TEMPE OFFICE
4500 S. LAKESHORE DRIVE
SUITE 339
TEMPE, ARIZONA 85282

RICHARD L. SALLQUIST

PHONE (480) 839-5202
FACSIMILE (480) 345-0412
E-MAIL dick@sd-law.com

September 4, 2007

HAND DELIVERY
Blessing Chukwu
Arizona Corporation Commission
Utilities Division
1200 W. Washington
Phoenix, AZ 85007

Arizona Corporation Commission
DOCKETED
SEP 04 2007

DOCKETED BY	
-------------	--

Re: Keaton Development Company-Docket No. W-02169A-07-0098; Fourth Insufficiency Response

Dear Blessing:

Please find enclosed the Company's response to your Insufficiency Letter of August 30, 2007.

Attached are the documents faxed to you on August 31, based on our telephonic discussion on the 29th. As indicated in that discussion, and demonstrated in my fax, the Company has timely requested the required Report. Unfortunately, we can not control the ADEQ response time, but expect a request by Commission Staff would result in an immediate response.

Could you please process this Application, issue a conditional Staff Report, and assume that ADEQ will respond before our as yet unset hearing date? As previously indicated, the Developer is very anxious to proceed with the project.

In the event you have any questions regarding these matters, please do not hesitate to call.

Sincerely,

Richard L. Sallquist

AZ CORP COMMISSION
DOCKET CONTROL

2007 SEP -4 P 12: 22

RECEIVED

Enclosure

Blessing Chukwu
September 4, 2007
Page 2

cc: Docket Control
Del Smith
Lyn Farmer
Brian Bozzo
Vicki Wallace
Bill Scott

SALLQUIST, DRUMMOND & O'CONNOR, P.C.

Tempe Office
4500 S. Lakeshore Drive
Suite 339
Tempe, Arizona 85282

F A X C O V E R S H E E T

DATE: August 31, 2007

TIME: 12:52 PM

TO: ADEQ Compliance

(602) 771-4505

CC:

FROM: Richard L. Sallquist

PHONE: (480) 839-5202

FAX: (480) 345-0412

E-MAIL: dick@sd-law.com

RE: Keaton Development

NUMBER OF PAGES INCLUDING COVER SHEET: 4

ACCOUNT NUMBER: 53001-00000

Gentlemen: This request was originally faxed to ADEQ on 4/30/07. Will you please process this as quickly as possible to facilitate a CC&N Application at the Commission for a very anxious developer. Thank you.
Dick

08/30/2007 09:41 FAX
Aug 30 07 09:06a

Devawn Olivieri

S D & O

928-859-3984

003/005

p. 3

ARIZONA CORPORATION COMMISSION STATUS REQUEST

DATE: 8-29-07

TO:
Arizona Department of Environmental Quality
Drinking Water Compliance Enforcement Unit
3033 N. Central Avenue, M0501B
Phoenix, Arizona 85012-2809
Phone: 602-207-4624
Fax: 602-207-4505

FROM: 771
Water Company: KEATON DEVELOPMENT CO
Mailing Address: PO Box 905
City, State, Zip Code: SALOME, AZ 85348
Phone Number: 928-859-3982
FAX: 928-859-3984

Please return completed request to ACC Utilities Engineering (FAX 602-542-2129) and to the Company at address listed above within 30 days.

Compliance Status Report

PWS Name: KEATON DEVELOPMENT CO
PWS ID #: PWS # 15-029

Overall Compliance Status: No Major Deficiencies Major Deficiencies
Comments:

Monitoring and Reporting Deficiencies: No Deficiencies Major Deficiencies
List deficiencies:

Operation and Maintenance Deficiencies: No Deficiencies Major Deficiencies
Date of last inspection / sanitary survey: _____

Major Operation and Maintenance Deficiencies cited during inspection
 None unable to maintain 20 psi inadequate storage
 cross connection/backflow problems surface water treatment rule
 treatment deficiencies approval of construction
 certified operator other

Comments:

Administrative Orders:
Is ADEQ administrative order in effect? Yes No
Is US EPA administrative order in effect? Yes No
Comments:

System Information:
Number of Points of Entry _____ Population Served _____ Connections Served _____

DWCE Evaluation completed by: _____

Phone: _____ Date: _____

Based on data submitted by the water system, ADEQ has determined that this system is currently delivering water that (meets/does not meet) water quality standards required by Arizona Administrative Code, Title 18, Chapter 4. This compliance status report does not guarantee the water quality for this system in the future. This compliance status report does not reflect the status of any other water system owned by this utility company.

08/30/2007 09:42 FAX
Aug 30 07 09:07a

Devawn Olivieri

S D & O

928-859-3984

005/005

p. 5

ARIZONA CORPORATION COMMISSION STATUS REQUEST

TO:

Arizona Department of Environmental Quality
Drinking Water Compliance Enforcement Unit
3033 N. Central Avenue, M0501B
Phoenix, Arizona 85012-2809
Phone: 602-207-4624
Fax: 602-207-4505

DATE: 4-11-07

FROM:

Water Company:
Mailing Address:
City, State, Zip Code
Phone Number:
FAX:

KEATON DEVELOPMENT CO
PO Box 905
SALOME, AZ 85398
928-859-3982
928-859-3982

Please return completed request to ACC Utilities Engineering (FAX 602-542-2129) and to the Company at address listed above within 30 days.

Compliance Status Report

PWS Name:

KEATON DEVELOPMENT CO

PWS ID #:

PWS # 15-029

Overall Compliance Status: No Major Deficiencies Major Deficiencies

Comments:

Monitoring and Reporting Deficiencies: No Deficiencies Major Deficiencies

List deficiencies:

Operation and Maintenance Deficiencies: No Deficiencies Major Deficiencies

Date of last inspection / sanitary survey: _____

Major Operation and Maintenance Deficiencies cited during inspection

- | | | |
|-------------------------------|---|---|
| <input type="checkbox"/> None | <input type="checkbox"/> unable to maintain 20 psi | <input type="checkbox"/> inadequate storage |
| | <input type="checkbox"/> cross connection/backflow problems | <input type="checkbox"/> surface water treatment rule |
| | <input type="checkbox"/> treatment deficiencies | <input type="checkbox"/> approval of construction |
| | <input type="checkbox"/> certified operator | <input type="checkbox"/> other |

Comments:

Administrative Orders:

Is ADEQ administrative order in effect? Yes No

Is US EPA administrative order in effect? Yes No

Comments:

System Information:

Number of Points of Entry _____ Population Served _____ Connections Served _____

DWCE Evaluation completed by: _____

Phone: _____ Date: _____

Based on data submitted by the water system, ADEQ has determined that this system is currently delivering water that (meets/does not meet) water quality standards required by Arizona Administrative Code, Title 18, Chapter 4. This compliance status report does not guarantee the water quality for this system in the future. This compliance status report does not reflect the status of any other water system owned by this utility company.

ITEM NO. 6