

ORIGINAL



0000084902

BEFORE THE ARIZONA CORPORATION

RECEIVED

57

COMMISSIONERS

2008 MAY 14 P 4:46

MIKE GLEASON, Chairman  
JEFF HATCH-MILLER  
WILLIAM A. MUNDELL  
KRISTIN K. MAYES  
GARY PIERCE

AZ CORP COMMISSION  
DOCKET CONTROL

IN THE MATTER OF THE APPLICATION  
OF ICR WATER USERS ASSOCIATION,  
INC. FOR DETERMINATION OF THE  
CURRENT FAIR VALUE OF ITS UTILITY  
PLANT AND PROPERTY AND FOR  
INCREASES IN ITS RATES AND  
CHARGES FOR UTILITY SERVICES

DOCKET NO. W-02824A-07-0388

**NOTICE OF FILING  
ENVIRONMENTAL  
COMPLIANCE STATUS REPORTS**

In this rate proceeding, Arizona Corporation Commission Staff has recommended several compliance conditions for ICR Water Users Association, Inc. ("ICR") to meet. One of Staff's recommendations requires ICR to demonstrate that it is in compliance with the Arizona Department of Environmental Quality ("ADEQ") before ICR's new rates can go into effect. (J. Liu's Direct Testimony, Exhibit JWL at 4-5 (November 30, 2007) and Surrebuttal Testimony at 2 (December 21, 2007).) To comply with Mr. Liu's recommendation, ICR encloses copies of Compliance Status Reports for its two water systems, System Nos. 13-263 and 13-303, showing that it is in full compliance with ADEQ. (Exhibit A.)

By satisfying this recommendation before the hearing date, ICR requests that Mr. Liu's recommendation be removed as a compliance condition to any future recommended opinion and order and decision in this matter.

RESPECTFULLY submitted this 14th day of May, 2008.

Arizona Corporation Commission  
**DOCKETED**

MAY 14 2008

DOCKETED BY nr

Snell & Wilmer

L.P.  
LAW OFFICES  
One Arizona Center, 400 E. Van Buren  
Phoenix, Arizona 85004-2202  
(602) 382-6000

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28

SNELL & WILMER



---


Robert J. Metli  
Marcie A. Shuman  
One Arizona Center  
Phoenix, Arizona 85004-2202  
Attorneys for ICR Water Users Association, Inc.

ORIGINAL AND THIRTEEN (13) copies  
filed this 14th day of May, 2008, with:

Docket Control  
ARIZONA CORPORATION COMMISSION  
1200 West Washington  
Phoenix, Arizona 85007

COPY of the foregoing mailed  
this 14th day of May, 2008, to:

Mr. Dayne Taylor  
13868 North Grey Bears Trail  
Prescott, AZ 86305



8768928.2

# **EXHIBIT A**

**Arizona Department of Environmental Quality**  
 Drinking Water Monitoring and Protection Unit  
 Mail Code 5415B-2  
 1110 West Washington Street  
 Phoenix, AZ 85007

### Drinking Water Compliance Status Report

System Name	System Type		Is system consecutive?	
ICR TALKING ROCK	X	Community		Yes, to PWS #
<b>System ID #</b>		Non-transient Non-community		
13263		Transient Non-community	X	No

<b>Overall compliance status</b>	X	No major deficiencies		Major deficiencies
<b>Monitoring and Reporting status</b>	X	No major deficiencies		Major deficiencies
Comments: None				

<b>Operation and Maintenance status</b>	X	No major deficiencies		Major deficiencies
<b>Date of last Sanitary Survey</b>	N/A	<b>Inspector</b>	N/A	
Major unresolved/ongoing operation and maintenance deficiencies:				
<input type="checkbox"/> unable to maintain 20psi		<input type="checkbox"/> inadequate storage		
<input type="checkbox"/> cross connection/backflow problems		<input type="checkbox"/> surface water treatment rule		
<input type="checkbox"/> treatment deficiencies		<input type="checkbox"/> approval to construct/of construction		
<input type="checkbox"/> certified operator		<input type="checkbox"/> other		
Comments: None				

<b>Is an ADEQ administrative order in effect?</b>		Yes	X	No
Comments: None				

System Information				
Population Served	550			
Service Connections	275			
Number of Entry Points to the Distribution System	1			
Number of Sources	3			
Initial Monitoring Year	2008			
Monitoring Assistance Program (MAP) System	X	Yes		No

<b>Evaluation completed by</b>	Donna Calderon, Manager  Drinking Water Monitoring and Protection Unit		
<b>Phone</b>	602-771-4641	<b>Date</b>	April 25, 2008
X	Based upon data submitted by the water system, ADEQ has determined that this system is currently delivering water that meets water quality standards required by Arizona Administrative Code, Title 18, Chapter 4.		
	Based upon the monitoring and reporting deficiencies noted above, ADEQ <b>cannot determine</b> if this system is currently delivering water that meets water quality standards required by Arizona Administrative Code, Title 18, Chapter 4.		
	Based upon the operation and maintenance deficiencies noted above, ADEQ <b>cannot determine</b> if this system is currently delivering water that meets water quality standards required by Arizona Administrative Code, Title 18, Chapter 4.		

***This compliance status report does not guarantee the water quality for this system in the future, and does not reflect the status of any other water system owned by this utility company.***

**Arizona Department of Environmental Quality**  
 Drinking Water Monitoring and Protection Unit  
 Mail Code 5415B-2  
 1110 West Washington Street  
 Phoenix, AZ 85007

### Drinking Water Compliance Status Report

System Name	System Type	Is system consecutive?
INSCRIPTION CANYON RANCH SYSTEM	X Community	Yes, to PWS #
	Non-transient Non-community	
System ID #	Transient Non-community	X No
13303		

Overall compliance status	X	No major deficiencies	Major deficiencies
Monitoring and Reporting status	X	No major deficiencies	Major deficiencies
Comments: None			

Operation and Maintenance status	X	No major deficiencies	Major deficiencies
Date of last Sanitary Survey	10/05/05	Inspector	Jim Jones, NRO
Major unresolved/ongoing operation and maintenance deficiencies:			
<input type="checkbox"/> unable to maintain 20psi		<input type="checkbox"/> inadequate storage	
<input type="checkbox"/> cross connection/backflow problems		<input type="checkbox"/> surface water treatment rule	
<input type="checkbox"/> treatment deficiencies		<input type="checkbox"/> approval to construct/of construction	
<input type="checkbox"/> certified operator		<input type="checkbox"/> other	
Comments: None			

Is an ADEQ administrative order in effect?		Yes	X	No
Comments: None				

System Information				
Population Served	100			
Service Connections	100			
Number of Entry Points to the Distribution System	1			
Number of Sources	2			
Initial Monitoring Year	1999			
Monitoring Assistance Program (MAP) System	X	Yes		No

Evaluation completed by	Donna Calderon, Manager  Drinking Water Monitoring and Protection Unit		
Phone	602-771-4641	Date	April 25, 2008
X	Based upon data submitted by the water system, ADEQ has determined that this system is currently delivering water that meets water quality standards required by Arizona Administrative Code, Title 18, Chapter 4.		
	Based upon the monitoring and reporting deficiencies noted above, ADEQ <b>cannot determine</b> if this system is currently delivering water that meets water quality standards required by Arizona Administrative Code, Title 18, Chapter 4.		
	Based upon the operation and maintenance deficiencies noted above, ADEQ <b>cannot determine</b> if this system is currently delivering water that meets water quality standards required by Arizona Administrative Code, Title 18, Chapter 4.		

***This compliance status report does not guarantee the water quality for this system in the future, and does not reflect the status of any other water system owned by this utility company.***