

ORIGINAL



0000085569

BEFORE THE ARIZONA CORPORATION COMMISSION

RECEIVED

6/5/08

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28

COMMISSIONERS

2008 JUN -5 P 2: 28

MIKE GLEASON, Chairman
WILLIAM A. MUNDELL
JEFF HATCH-MILLER
KRISTIN K. MAYES
GARY PIERCE

AZ CORP COMMISSION
DOCKET CONTROL

IN THE MATTER OF THE APPLICATION OF
NORTH MOHAVE VALLEY CORPORATION
FOR AN EXTENSION OF ITS CERTIFICATE
OF CONVENIENCE AND NECESSITY TO
PROVIDE WATER SERVICE IN MOHAVE
COUNTY, ARIZONA.

DOCKET NO. W-02259A-07-0434

NOTICE OF FILING

Staff hereby files on behalf of North Mohave Valley Corporation ("NMVC"), the Company's most recent Drinking Water Compliance Status Report.

RESPECTUFLY SUBMITTED this 5th day of June, 2008.

Robin K. Mitchell
Attorney, Legal Division
Arizona Corporation Commission
1200 W. Washington St.
Phoenix, AZ 85007
(602) 542-3402

Original and thirteen (13) copies of the foregoing were filed this 5th day of June, 2008 with:

Docket Control
Arizona Corporation Commission
1200 West Washington Street
Phoenix, Arizona 85008

Copy of the foregoing mailed this 5th day of June, 2008 to:

John McCormick
Secretary-Treasurer/Manager
North Mohave Valley Corporation
P.O. Box 22495
Bullhead City, Arizona 86439-2495

Arizona Corporation Commission
DOCKETED

JUN -5 2008

DOCKETED BY

Terrence S. Leek, Esq.
Law Office of Terrence S. Leek, P.C.
126 North Marina Street
Prescott, Arizona 86301

Arizona Department of Environmental Quality
Drinking Water Monitoring and Protection Unit
1110 W. Washington Street, 5415B-1
Phoenix, AZ 85007

Drinking Water Compliance Status Report

Public Water System Name: North Mohave Valley Water Corp.

Public Water System ID #: 08-068

Public Water System Type: Community Non-transient Non-community Transient Non-community

Overall Compliance Status: No Major Deficiencies Major Deficiencies

Monitoring and Reporting Status: No Major Deficiencies Major Deficiencies

Comments:

Lead and Copper - System has missed two triennial monitoring periods for lead and copper. System is required to sample once every three years beginning in 2005. Based upon a change in population in 2004, the number of samples required is now 20 of each, every three years.

Operation and Maintenance Status: No Major Deficiencies Major Deficiencies

Comments:

Major unresolved/ongoing operation and maintenance deficiencies:

- | | |
|-------------------------------------------------------------|-------------------------------------------------------|
| <input type="checkbox"/> unable to maintain 20psi | <input type="checkbox"/> inadequate storage |
| <input type="checkbox"/> cross connection/backflow problems | <input type="checkbox"/> surface water treatment rule |
| <input type="checkbox"/> treatment deficiencies | <input type="checkbox"/> approval of construction |
| <input type="checkbox"/> certified operator | <input type="checkbox"/> other |

Date of last inspection / sanitary survey: 1-24-08

Administrative Orders:

Is an ADEQ administrative order in effect? Yes No

Comments:

System information:

Number of Entry Points to the Distribution System 2 Number of Sources 10

Population Served 4678 Service Connections 1933 Initial Monitoring Year 1994

Evaluation completed by: Donna Calderon, Manager, Drinking Water Monitoring and Protection Unit

Phone: 602-771-4641

Date: February 25, 2008

Based upon the monitoring deficiencies, ADEQ cannot determine if this system is currently delivering water that meets water quality standards required by Arizona Administrative Code, Title 18, Chapter 4. This compliance status report does not guarantee the water quality for this system in the future. This compliance status report does not reflect the status of any other water system owned by this utility company