



0000088209

ORIGINAL

BEFORE THE ARIZONA CORPORATION COMMISSION
RECEIVED

57

2 COMMISSIONERS

- 3 MIKE GLEASON, Chairman
- 4 WILLIAM A. MUNDELL
- 5 JEFF HATCH-MILLER
- 6 KRISTIN K. MAYES
- 7 GARY PIERCE

2008 SEP -4 P 1:45

AZ CORP COMMISSION
DOCKET CONTROL

6 IN THE MATTER OF THE APPLICATION OF
7 NORTH MOHAVE VALLEY CORPORATION
8 FOR AN EXTENSION OF ITS CERTIFICATE
9 OF CONVENIENCE AND NECESSITY TO
10 PROVIDE WATER SERVICE IN MOHAVE
11 COUNTY, ARIZONA.

DOCKET NO. W-02259A-07-0434

NOTICE OF FILING

10 Staff hereby files on behalf of North Mohave Valley Corporation ("NMVC"), the Company's
11 updated Arizona Department of Environmental Quality Report ("ADEQ").

12 RESPECTFULLY SUBMITTED this 4th day of September, 2008.

13
14
15 Robin R. Mitchell
16 Attorney, Legal Division
17 Arizona Corporation Commission
18 1200 W. Washington St.
19 Phoenix, AZ 85007
20 (602) 542-3402

Arizona Corporation Commission
DOCKETED

SEP - 4 2008

19 Original and thirteen (13) copies
20 of the foregoing were filed this
21 4th day of September, 2008 with:

21 Docket Control
22 Arizona Corporation Commission
23 1200 West Washington Street
24 Phoenix, Arizona 85008

25 Copy of the foregoing mailed this
26 4th day of September, 2008 to:

25 John McCormick
26 Secretary-Treasurer/Manager
27 North Mohave Valley Corporation
28 P.O. Box 22495
Bullhead City, Arizona 86439-2495

Terrence S. Leek, Esq.
Law Office of Terrence S. Leek, P.C.
126 North Marina Street
Prescott, Arizona 86301
Attorney for North Mohave Valley Corporation

28

DOCKETED BY	
-------------	--

Arizona Department of Environmental Quality
 Drinking Water Monitoring and Protection Unit
 Mail Code 5415B-2
 1110 West Washington Street
 Phoenix, AZ 85007

Drinking Water Compliance Status Report

System Name	System Type	Is system consecutive?	
NORTH MOHAVE VALLEY WATER CORPORATION	X Community		Yes, to PWS #
System ID #	Non-transient Non-community		
08068	Transient Non-community	X	No

Overall compliance status	X	No major deficiencies	Major deficiencies
Monitoring and Reporting status	X	No major deficiencies	Major deficiencies
Comments: None			

Operation and Maintenance status	X	No major deficiencies	Major deficiencies
Date of last Sanitary Survey	1/24/08	Inspector	Andy Wilson, NRO
Major unresolved/ongoing operation and maintenance deficiencies:			
<input type="checkbox"/> unable to maintain 20psi	<input type="checkbox"/> inadequate storage	<input type="checkbox"/> surface water treatment rule	<input type="checkbox"/> approval to construct/of construction
<input type="checkbox"/> cross connection/backflow problems	<input type="checkbox"/> other		
<input type="checkbox"/> treatment deficiencies			
<input type="checkbox"/> certified operator			
Comments: None			

Is an ADEQ administrative order in effect?		Yes	X	No
Comments: None.				

System Information			
Population Served	4806		
Service Connections	1986		
Number of Entry Points to the Distribution System	2		
Number of Sources	10		
Initial Monitoring Year	1994		
Monitoring Assistance Program (MAP) System	X	Yes	No

Evaluation completed by	Donna Calderon, Manager  Drinking Water Monitoring and Protection Unit		
Phone	602-771-4641	Date	September 4, 2008
X	Based upon data submitted by the water system, ADEQ has determined that this system is currently delivering water that meets water quality standards required by Arizona Administrative Code, Title 18, Chapter 4.		
	Based upon the monitoring and reporting deficiencies noted above, ADEQ cannot determine if this system is currently delivering water that meets water quality standards required by Arizona Administrative Code, Title 18, Chapter 4.		
	Based upon the operation and maintenance deficiencies noted above, ADEQ cannot determine if this system is currently delivering water that meets water quality standards required by Arizona Administrative Code, Title 18, Chapter 4.		

This compliance status report does not guarantee the water quality for this system in the future, and does not reflect the status of any other water system owned by this utility company.