



No. 3426 ORIGINAL

W-02386A-09-0308

RECEIVED Arizona Dept. of Environment
Drinking Water Monitoring and Protection Unit
2009 JUL 27 P 4: 12
Mail Code 5415B-2
1110 West Washington Street
Phoenix, AZ 85007

AZ CORP COMMISSION
DOCKET CONTROL

Drinking Water Compliance Status Report

System Name SUN LEISURE EST UTIL CO	System Type <input checked="" type="checkbox"/> Community <input type="checkbox"/> Non-transient Non-community <input type="checkbox"/> Transient Non-community	Is system consecutive? <input type="checkbox"/> Yes to PWS # <input checked="" type="checkbox"/> No
System ID # 14075		

Overall compliance status	<input checked="" type="checkbox"/> No major deficiencies	<input type="checkbox"/> Major deficiencies
Monitoring and Reporting status	<input checked="" type="checkbox"/> No major deficiencies	<input type="checkbox"/> Major deficiencies
Comments: None		

Operation and Maintenance status	<input checked="" type="checkbox"/> No major deficiencies	<input type="checkbox"/> Major deficiencies
Date of last Sanitary Survey	1-10-07	Inspector Stephen Devereaux, SRO

Major unresolved/ongoing operation and maintenance deficiencies:

<input type="checkbox"/> unable to maintain 20psi	<input type="checkbox"/> inadequate storage
<input type="checkbox"/> cross connection/backflow problems	<input type="checkbox"/> surface water treatment rule
<input type="checkbox"/> treatment deficiencies	<input type="checkbox"/> ATC/AOC
<input type="checkbox"/> certified operator	<input type="checkbox"/> other =

Arizona Corporation Commission
DOCKETED

JUL 27 2009

Comments: None

DOCKETED BY

Is an ADEQ administrative order in effect?	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Comments: None		

System Information

Population Served	116
Service Connections	58
Number of Entry Points to the Distribution System	1
Number of Sources	1
Initial Monitoring Year	1995
Monitoring Assistance Program (MAP) System	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No

Evaluation completed by	Donna Calderon, Manager Drinking Water Monitoring and Protection Unit		
Phone	602-771-4641	Date	April 30, 2009
<input checked="" type="checkbox"/>	Based upon data submitted by the water system, ADEQ has determined that this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4, and PWS is in compliance.		
<input type="checkbox"/>	Based upon the monitoring and reporting deficiencies noted above, ADEQ cannot determine if this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4, and/or PWS is not in compliance.		
<input type="checkbox"/>	Based upon the operation and maintenance deficiencies noted above, ADEQ cannot determine if this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4, and/or PWS is not in compliance.		

This compliance status report does not guarantee the water quality for this system in the future, and does not reflect the status of any other water system owned by this utility company.