



0000150553

RECEIVED

2013 DEC 27 P 12:07

ARIZONA CORP COMMISSION
DOCKET CONTROL

1 COMMISSIONERS
2 BOB STUMP – Chairman
3 GARY PIERCE
4 BRENDA BURNS
5 BOB BURNS
6 SUSAN BITTER SMITH

ORIGINAL

BEFORE THE ARIZONA CORPORATION COMMISSION

7 IN THE MATTER OF THE APPLICATION
8 OF MONTEZUMA RIMROCK WATER
9 COMPANY, LLC FOR APPROVAL OF
10 FINANCING TO INSTALL A WATER LINE
FROM THE WELL ON TIEMAN TO WELL
NO. 1 ON TOWERS.

Docket No. W-04254A-12-0204

11 IN THE MATTER OF THE APPLICATION
12 OF MONTEZUMA RIMROCK WATER
13 COMPANY, LLC FOR APPROVAL OF
FINANCING TO PURCHASE THE WELL
NO. 4 SITE AND THE COMPANY
VEHICLE.

Docket No. W-04254A-12-0205

14 IN THE MATTER OF THE APPLICATION
15 OF MONTEZUMA RIMROCK WATER
16 COMPANY, LLC FOR APPROVAL OF
FINANCING FOR AN 8,000-GALLON
HYDRO-PNEUMATIC TANK.

Docket No. W-04254A-12-0206

17 IN THE MATTER OF THE RATE
18 APPLICATION OF MONTEZUMA
RIMROCK WATER COMPANY, LLC.

Docket No. W-04254A-12-0207

19 JOHN E. DOUGHERTY,
20
21 COMPLAINANT,

Docket No. W-04254A-11-0323

22 V.
23 MONTEZUMA RIMROCK WATER
COMPANY, LLC

24 RESPONDENT

Arizona Corporation Commission
DOCKETED

DEC 27 2013

DOCKETED BY

1 IN THE MATTER OF THE APPLICATION
2 OF MONTEZUMA RIMROCK WATER
3 COMPANY, LLC FOR APPROVAL OF A
RATE INCREASE.

Docket No. W-04254A -08-0361

4 IN THE MATTER OF THE APPLICATION
5 OF MONTEZUMA RIMROCK WATER
6 COMPANY, LLC FOR APPROVAL OF A
FINANCING APPLICATION.

Docket No. W-04254A -08-0362


**NOTICE OF FILING
COMPLIANCE STATUS REPORT**

7 Montezuma Rimrock Water Company LLC ("MRWC" or "Company") hereby
8 files a copy of the Drinking Water Compliance Status Report issued by The Arizona
9 Department of Environmental Quality on December 19, 2013. As set forth in that
10 Compliance Status Report, the Company's quarterly compliance samples for its arsenic
11 treatment plant show "more than a year of data with all results beneath the MCL." As
12 stated in the attached report, MRWC is in compliance with ADEQ's Administrative Order
13 relating to arsenic levels and testing.

14 RESPECTFULLY SUBMITTED this day 27th of December, 2013.

15 FENNEMORE CRAIG

16
17
18 By


Todd C. Wiley
2394 E. Camelback Road, Suite 600
Phoenix, AZ 85016
Attorneys for Montezuma Rimrock Water
Company, LLC.

19
20
21
22 An original and 13 copies
23 of the foregoing was filed
this 27th day of December, 2013,
24 with:

25 Docket Control
Arizona Corporation Commission
1200 West Washington Street
26 Phoenix, Arizona 85007

1 A copy of the foregoing
was hand delivered/mailed/mailed this
2 27th day of December, 2013, to:

3 Sarah N. Harpring
Administrative Law Judge
4 Arizona Corporation Commission
1200 W. Washington
5 Phoenix, Arizona 85007

6 Charles Hains
Wes Van Cleve
7 Legal Division
Arizona Corporation Commission
8 1200 W. Washington
Phoenix, Arizona 85007

9 Steve Olea
10 Utilities Division
Arizona Corporation Commission
11 1200 W. Washington
Phoenix, Arizona 85007

12 John E. Dougherty, III
13 P.O. Box 501
14 Rimrock, Arizona 86335

15 
16 _____

8757933.1/028469.0003

17
18
19
20
21
22
23
24
25
26

ATTACHMENT

Arizona Department of Environmental Quality
Drinking Water Monitoring and Protection Unit
 Mail Code 5415B-2
 1110 West Washington Street
 Phoenix, AZ 85007

Drinking Water Compliance Status Report

System Name	System Type	Is system consecutive?
MONTEZUMA RIMROCK WC LLC	<input checked="" type="checkbox"/> Community	<input type="checkbox"/> Yes, to PWS #
System ID #	<input type="checkbox"/> Non-transient Non-community	<input checked="" type="checkbox"/> No
13071	<input type="checkbox"/> Transient Non-community	

Overall compliance status	<input checked="" type="checkbox"/> No major deficiencies	<input type="checkbox"/> Major deficiencies
Monitoring and Reporting status	<input checked="" type="checkbox"/> No major deficiencies	<input type="checkbox"/> Major deficiencies

Comments: The PWS was issued an Approval of Construction on 11/21/12 for a new arsenic treatment plant. Compliance for the arsenic standard is determined by the running annual average of quarterly compliance samples. The PWS now has more than a year of data with all results beneath the MCL.

Operation and Maintenance status	<input checked="" type="checkbox"/> No major deficiencies	<input type="checkbox"/> Major deficiencies
Date of last Sanitary Survey	12-10-12	Inspector
		Steve Camp, PHX

Major unresolved/ongoing operation and maintenance deficiencies:

- | | |
|---|--|
| <input type="checkbox"/> unable to maintain 20psi | <input checked="" type="checkbox"/> inadequate storage |
| <input type="checkbox"/> cross connection/backflow problems | <input type="checkbox"/> surface water treatment rule |
| <input type="checkbox"/> treatment deficiencies | <input type="checkbox"/> ATC/AOC |
| <input type="checkbox"/> certified operator | <input type="checkbox"/> other = |

Comments: Minor deficiency for Finished Water Storage (need to provide the water system with a storage tank), no NOC issued.

Is an ADEQ administrative order in effect?	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Comments: Compliance Order DW-14-10 was issued 2-25-10 still in effect.		

System Information

Population Served	429
Service Connections	209
Number of Entry Points to the Distribution System	2
Number of Sources	2
Initial Monitoring Year	1995
Monitoring Assistance Program (MAP) System	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No

Evaluation completed by	Donna Calderon, Manager 		
	Drinking Water Monitoring and Protection Unit		
Phone	602-771-4641	Date	December 19, 2013
<input checked="" type="checkbox"/>	Based upon data submitted by the water system, ADEQ has determined that this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4, and PWS is in compliance.		
<input type="checkbox"/>	Based upon the monitoring and reporting deficiencies noted above, ADEQ cannot determine if this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4, and/or PWS is not in compliance.		
<input type="checkbox"/>	Based upon the operation and maintenance deficiencies noted above, ADEQ cannot determine if this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4, and/or PWS is not in compliance.		

This compliance status report does not guarantee the water quality for this system in the future, and does not reflect the status of any other water system owned by this utility company.